PartSmith repair card

Toothed cable strap

Family: cable_clip

BEST EFFORT

Max error: 1.76 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.959, Hausdorff 0.32 mm, mean 0.14 mm
side: IoU 0.901, Hausdorff 1.76 mm, mean 0.21 mm
Part tests: 17/18 passed
- top: refined in the photo frame by +0.04 deg, (-0.38, +0.43) mm on the mat
- side: refined in the photo frame by +0.12 deg, (+0.09, -0.06) mm on the mat
- top view (photo frame): IoU 0.959 (not gated), mean contour distance 0.14 mm (needs <= 0.15 mm), Hausd

Key dimensions

Length: 34.45 mm ± 0.10 [measured]
Width: 11.91 mm ± 0.10 [measured]
Thickness: 2.50 mm ± 0.30 [user stated]
hole_1 Ø: 3.45 mm ± 0.06 [measured]
hole_2 Ø: 3.42 mm ± 0.07 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: no
Orientation: -Z: mounting face (Z=0) on the bed, as modelled

Repair passport

9JCY23

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/9JCY23

Or type the id on the PartSmith site at /p/<id>. No new photos needed.