SYNTHETIC — not a real-world measurement

PartSmith repair card

Hinge leaf

Family: hinge

BEST EFFORT

Max error: 0.38 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.988, Hausdorff 0.38 mm, mean 0.08 mm
side: IoU 0.968, Hausdorff 0.27 mm, mean 0.08 mm
Part tests: 24/24 passed
Judge vetoes: 1 blocking
- top: refined in the photo frame by -0.01 deg, (-0.00, +0.03) mm on the mat
- side: refined in the photo frame by +0.08 deg, (-0.09, +0.15) mm on the mat
- top view (photo frame): IoU 0.988 (needs >= 0.97), Hausdorff 0.38 mm (needs <= 0.5 mm)

Key dimensions

Length: 58.54 mm ± 0.13 [measured]
Width: 29.67 mm ± 0.12 [measured]
Thickness: 2.50 mm ± 0.30 [user stated]
hole_1 Ø: 4.23 mm ± 0.01 [measured]
hole_2 Ø: 4.25 mm ± 0.01 [measured]
hole_3 Ø: 4.27 mm ± 0.02 [measured]
hole_4 Ø: 4.23 mm ± 0.02 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: +X: +X end on the bed

Repair passport

G68XS6

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/G68XS6

Or type the id on the PartSmith site at /p/<id>. No new photos needed.