

Federal Safety & Compliance Regulation: OISD-STD-189

Document: OISD-STD-189. Category: Safety Legislation.

This document outlines mandatory guidelines for isolation procedures and lockout safety in industrial distillation plants.

Rule 12.1: Electrical Isolation (LOTO) Rule 12.1: Electrical switchgear panels must be isolated and locked out (LOTO) using physical padlocks prior to starting mechanical repair on heavy pumps. No technician shall work on pump systems like P-204 without LOTO confirmation.

Rule 12.2: Stale Safety SOP Reviews Rule 12.2: Governing safety procedures and LOTO checklists must be reviewed and re-approved by the plant manager annually to ensure procedures are not stale.

Rule 12.3: Unresolved Non-Conformance checks Rule 12.3: Plant supervisors must verify that any active LOTO incidents or safety non-conformance records on equipment like pump P-204 are resolved before resuming operational status.