

Lot ISRO-26-091 • Burn-in cycle • 168h final

Parts screened

1,248

+8.2%

PASS

1,108

88.8%

REVIEW

96

7.7%


REJECT

44

3.5%

Lot distribution

Leakage current • 168h • μA



Combined verdict

Module A + Module B

PASS

1,108

Normal / within limits

REVIEW

96

Inspector decision needed

REJECT

44

Limit, outlier or drift

Priority alerts

Highest-risk parts requiring inspector attention

P-0917

Predicted 168h leakage 47.2 μA • steep drift

P-1042

Lot-relative anomaly score 4.8 • multi-parameter

Inspector view

Every flag links the drift curve, lot distribution and evidence behind the decision.

96 in review queue

SYSTEM

Last sync 09:42 UTC

LIVE

- Overview
- Lot Analysis
- Part Detail
- Review Queue
- Trends
- Model Performance

Compare lot behaviour, distributions and burn-in progression

LOT
ISRO-26-091

1,248 parts • 4 measurements • 168h final

Export lot report

Lot baseline

10.4 μA

MAD spread

1.9 μA

Anomalies


140

Drift flags

74

Lot distribution by measurement


Median $\pm$ robust spread (MAD)



Outliers beyond the robust band are highlighted for Module A review.

Lot mean trend

μA over burn-in hours



Recent lots

Lot	Parts	Anomaly rate	Drift rate	Status
ISRO-26-091	1,248	11.2%	5.9%	Monitoring
ISRO-26-090	1,196	8.6%	4.1%	Stable

Explainable inspection view • evidence behind the model decision

REVIEW

Part P-1042

Lot ISRO-26-091 • Position 1042 / 1248

Anomaly score

4.8

Predicted 168h

47.2 μ A

Leakage current drift

Part vs lot median • μ A



Why this part was flagged

Three signals drive the REVIEW decision.

Lot-relative outlier

4.8 MAD

Primary

24h $\rightarrow$ 168h drift

+31.6 μ A

Primary

Iddq + delay

Both elevated

Secondary

Inspector evidence

Module A: part is far from its lot centre. Module B: early readings imply a steep final drift.

Open review decision

Borderline parts awaiting an inspector decision

Search part ID or lot

All 96

High risk 18

Unassigned 34

Filters

Part	Lot	Verdict	Anomaly	Pred. 168h	Primary reason	Action
P-1042	ISRO-26-091	REVIEW	4.8	47.2 μ A	Steep drift	Open
P-0917	ISRO-26-091	REVIEW	4.2	45.8 μ A	Lot outlier	Open
P-0771	ISRO-26-091	REVIEW	3.9	39.1 μ A	Multi-parameter	Open
P-1180	ISRO-26-090	REVIEW	3.6	36.8 μ A	Iddq elevated	Open
P-0144	ISRO-26-090	REVIEW	3.2	34.9 μ A	Propagation delay	Open
P-0612	ISRO-26-089	REVIEW	3.0	31.6 μ A	Lot outlier	Open

- Overview
- Lot Analysis
- Part Detail
- Review Queue
- Trends
- Model Performance

SYSTEM

Last sync 09:42 UTC

LIVE

Export

Monitor anomaly rates across lots, suppliers and burn-in cycles

Anomaly rate

11.2%
↓ 1.8 pp

Drift rate

5.9%
↓ 0.7 pp

False negatives


1.6%
Target < 2%

Lots monitored

38
+4 this month

Anomaly rate by lot

Last 12 lots • percentage of parts flagged



Supplier anomaly rate



Measurement risk by burn-in point

	0h	24h	96h	168h
Leakage	Low	Watch	Watch	High
Iddq	Low	Watch	High	High
Propagation delay	Low	Low	Watch	High

- Overview
- Lot Analysis
- Part Detail
- Review Queue
- Trends
- Model Performance

SYSTEM

Last sync 09:42 UTC

LIVE

Export

Validation metrics for Module A, Module B and combined decisions

Module A recall

96.4%

False negatives 1.6%

Module B MAE

3.8 μ A

Held-out validation

Precision

91.2%


Review-first threshold

Model version

v2.4.1

Validated 26 Sep

Module A • outlier detector



Held-out decision matrix

	Actual normal	Actual defect
Pred normal	1,842	31
Pred defect	82	812

Module B • drift predictor


Predicted 168h vs actual



MAE 3.8 μ A

Gradient boosting • linear baseline retained

Top explanation features



Model registry

v2.4.1	Current	26 Sep
v2.4.0	Archived	18 Sep
v2.3.2	Archived	02 Sep