

Safety Procedures — Brookhaven Dairy Processing Facility

Madison, WI · Document ID: BDP-SAF-001 · Revision 3 · Effective 01 Feb 2026

Document ID	BDP-SAF-001	Revision	3
Plant	Brookhaven Dairy Processing Facility	Effective Date	01 Feb 2026
Document Owner	Food Safety & Safety Coordinator: J. Halverstad	Classification	Controlled — Site Use

1. Purpose & Scope

This document covers personnel safety procedures at Brookhaven Dairy Processing Facility (Madison, WI). Scope includes raw milk receiving, HTST pasteurization, separation, packaging, CIP utilities, and the ammonia refrigeration plant. Conforms with FDA PCHF (21 CFR 117), Grade A PMO, and OSHA PSM (applicable due to >10,000 lb anhydrous ammonia inventory).

2. Regulatory & Standards Basis

Applicable: FDA 21 CFR 117 (PCHF), USDA, Grade A PMO.

3. Site Hazard Inventory

The principal site hazards at Brookhaven Dairy Processing Facility (Madison, WI) include: ammonia refrigerant (PSM), pasteurizer steam, allergen cross-contact. The full hazard inventory is summarized below; refer to the linked SOPs for detailed controls.

ID	Hazard	Primary Control
H-01	Anhydrous ammonia	PSM-covered; SCBA required for entry; LEL/PEL monitoring continuous.
H-02	Pasteurizer steam (180 PSI)	LOTO and steam trap isolation per LOTO-BDP-008.
H-03	Wet/slippery floors	Mandatory slip-resistant footwear; drain inspection every shift.
H-04	Allergen cross-contact (milk)	Color-coded tools; not a personal hazard but a food safety control.
H-05	Caustic CIP solutions (NaOH 2-3%)	Face shield, gloves; eyewash within 10 seconds of point of use.

4. Procedures

4.1 Ammonia Release Response

Detector alarms at 25 ppm (alert) and 150 ppm (evacuate). Engine room ventilation interlocked. Only IIPP-trained responders may attempt isolation. Refer to ERP-BDP-001.

4.2 LOTO on Pasteurizer

Steam, hot water, product, and CIP lines must be isolated and bled. Pasteurizer divert valve placed in manual divert position before LOTO confirms isolation.

4.3 Slip/Trip/Fall Prevention

Wet area mapping updated quarterly. Drain blockages reported to Sanitation within one shift. Floor coating integrity inspected per maintenance routine MNT-BDP-PM-12.

4.4 Training

All production employees: 8 hours initial GMP and safety; 4 hours annual refresh. Ammonia handlers: additional 24 hours RAGAGEP training plus annual re-qualification.

5. Roles & Responsibilities

The Food Safety & Safety Coordinator owns this procedure. Line Supervisors are accountable for daily compliance. Employees and contractors are responsible for stopping work in the event of an unsafe condition (Stop Work Authority).

6. References

- FDA 21 CFR Part 117 — PCHF
- Grade A Pasteurized Milk Ordinance (PMO)
- OSHA 29 CFR 1910.119 — PSM (Ammonia)
- ANSI/IIAR 2, 6, 7, 8 — Ammonia Refrigeration
- Internal: ERP-BDP-001, LOTO-BDP-008, MNT-BDP-PM-12

7. Revision History

Rev	Date	Author	Summary
1	12 Mar 2024	J. Halverson	Initial issue.
2	08 Aug 2025	J. Halverson	Added confined-space monitoring requirements.
3	01 Feb 2026	J. Halverson	Annual review; aligned with updated regulator guidance.

Approvals

Role	Name	Signature	Date
Food Safety & Safety Coordinator	J. Halverson	_____	01 Feb 2026
Quality Assurance	P. Mendez, QA Supervisor	_____	01 Feb 2026
Operations / Site Lead	C. Larsson, Plant Manager	_____	01 Feb 2026

CONFIDENTIAL — Controlled Document. Uncontrolled when printed. Reproduction outside the parent organization requires written authorization.