

Safety Procedures — Helix Pharmaceuticals Building 4

Cambridge, MA · Document ID: HLX-SAF-001 · Revision 3 · Effective 01 Feb 2026

Document ID	HLX-SAF-001	Revision	3
Plant	Helix Pharmaceuticals Building 4	Effective Date	01 Feb 2026
Document Owner	EHS Manager: S. Olusegun	Classification	Controlled — Site Use

1. Purpose & Scope

This SOP defines occupational safety and biocontainment procedures for Helix Pharmaceuticals Building 4, a small-molecule and ADC manufacturing site. It applies to BSL-2 suites, Grade B/C cleanrooms, and supporting utility spaces. Conforms with FDA 21 CFR 211 cGMP and EU Annex 1 (2022 revision).

2. Regulatory & Standards Basis

Applicable: FDA 21 CFR Part 210/211, EU GMP Annex 1, 21 CFR Part 11.

3. Site Hazard Inventory

The principal site hazards at Helix Pharmaceuticals Building 4 (Cambridge, MA) include: biological agents BSL-2, cytotoxic APIs, sterile environment integrity. The full hazard inventory is summarized below; refer to the linked SOPs for detailed controls.

ID	Hazard	Primary Control
H-01	Cytotoxic API exposure	OEB 4-5; isolator-only handling; full PPE per PPE-HLX-007.
H-02	Biological agents BSL-2	Class II BSC; no aerosol-generating operations on open bench.
H-03	Cleanroom particulate/microbial	Gowning per GWN-HLX-002; viable monitoring per ENV-HLX-010.
H-04	Solvents (acetonitrile, DMSO)	Local exhaust ventilation; SDS posted at point of use.
H-05	Cryogenic LN2 in QC lab	Splash shield, gloves; oxygen depletion sensor present.

4. Procedures

4.1 Gowning and Entry

Personnel enter Grade B/C suites through a 3-stage airlock following GWN-HLX-002. Gowning qualification re-confirmed every 6 months via settle plate and contact plate study.

4.2 Spill Response

Cytotoxic spills: clear area, don OEB-rated PPE, use cytotoxic spill kit (SPL-HLX-04), decontaminate with 0.1 N NaOH then 70% IPA. Notify EHS within 1 hour. Document on Form HLX-EHS-22.

4.3 Deviation Reporting

All safety deviations entered into the eQMS within 24 hours. Critical safety deviations trigger immediate containment, CAPA, and notification per QA-HLX-101.

4.4 Emergency Egress

Cleanroom egress overrides gowning protocol. Emergency doors trigger area decontamination workflow on re-entry per ENV-HLX-010.

5. Roles & Responsibilities

The EHS Manager owns this procedure. Line Supervisors are accountable for daily compliance. Employees and contractors are responsible for stopping work in the event of an unsafe condition (Stop Work Authority).

6. References

- FDA 21 CFR Part 210/211 — cGMP
- EU GMP Annex 1 (2022) — Manufacture of Sterile Medicinal Products
- OSHA 29 CFR 1910.1450 — Lab Standard
- Internal: GWN-HLX-002, PPE-HLX-007, ENV-HLX-010, QA-HLX-101

7. Revision History

Rev	Date	Author	Summary
1	12 Mar 2024	S. Olusegun	Initial issue.
2	08 Aug 2025	S. Olusegun	Added confined-space monitoring requirements.
3	01 Feb 2026	S. Olusegun	Annual review; aligned with updated regulator guidance.

Approvals

Role	Name	Signature	Date
EHS Manager	S. Olusegun	_____	01 Feb 2026
Quality Assurance	L. Hartmann, Head of Quality	_____	01 Feb 2026
Operations / Site Lead	A. Nakamura, Site Head	_____	01 Feb 2026

CONFIDENTIAL — Controlled Document. Uncontrolled when printed. Reproduction outside the parent organization requires written authorization.