



Tangail kiln signal

ENSEMBLE CONFIDENCE

74%

COMPLIANCE SCREEN

High-concern screen

RULE COVERAGE

2 flagged / 2 missing

KILN CLASS

CFCBK

COORDINATES

24.32610, 90.01440

IMAGERY

EOX Sentinel-2 Cloudless, 2024 annual composite

GROUND RESOLUTION

Approx. 10 m

Compliance rule screen

FLAGGED	Potential residential buffer conflict	Section 8(3)(a)
FLAGGED	Kiln technology screen	DoE cleaner-technology guidance
UNKNOWN	Licence and clearance record	Authority licence and environmental-clearance records
UNKNOWN	Prohibited land-use check	Section 8(1)

Verification context

Prepared settlement proximity: 0.7 km

Licence / clearance registry: not-checked

FIELD VERIFICATION REQUIRED

This brief contains replayed model outputs and screening rules. It does not determine that a kiln is illegal. Verify identity, location boundaries, household counts, licence and clearance records, field conditions, exceptions, and current law before action.