Home ► Spring Semester - 2021 ► Departments ► Electrical Engineering ► Power System Lab (EE39002) - Spring 2021 ► Lab Quiz ► Lab Quiz on all experiments

	7
Question	
Ouesuon	

Answer saved

Marked out of 2

What will be the operating time of an overcurrent relay following IEEE very inverse characteristic for a fault current of 600 A? Consider the pickup setting and TMS setting of the relay as 150 A and 1.5 respectively.


- ☐ a. 2 s
- ☐ b. 3.5 s
- ☐ c. 1.6 s
- ✓ d. 2.7 s



Answer saved

Marked out of 2

In a distribution system two adjacent relays have same CT ratios, 10:1. For a fault in the downstream of the two relays, the primary of the CTs see 300A current. Relay remote from the substation has pickup setting of 3 A and time multiplier setting (TMS) of 0.1. The other relay has pickup setting of 6 A and TMS setting of 0.3. Find the difference between the decision times by the two relays, which follow the following characteristics (shown in the plots).



Select one or more:

- ☐ a. 0.3 s
- ☐ b. 0.1 s
- ✓ c. 0.2 s
- ☐ d. 0.4 s

Ouestion 3

Answer saved

Marked out of 2

Overcurrent relay coordination provides

- a. (A) Minimum fault current
- b. Pickup settings
- c. high speed fault clearance
- ☐ d. Selectivity



Answer saved

Marked out of 2

Which of following information is not required to obtain pickup setting of overcurrent relay?

Select one or more:

- ✓ a. Ratio of the CT connecting the relay
- ✓ b. Maximum fault current level
- c. Maximum load current level
- ☐ d. Minimum fault current level


Question 5

Answer saved

Marked out of 2

In a distribution system two adjacent relays have same CT ratios, 50:5. For a fault in the downstream of the two relays, the primary of the CTs see 100A current. Relay remote from the substation has pickup setting of 1 Aand time multiplier setting (TMS) of 0.1. The other relay has pickup setting of 2 A. If the coordination time interval between the two relays is

0.3 s, find the TMS setting of the relay nearer to substation, which follow the following characteristics (shown in the plots).



- a. 0.1
- **b**. 0.3
- ☐ c. 0.4
- ☐ d. 0.2




Ouestion 6

Answer saved

Marked out of 2

For the fault shown at F in the diagram, as the best option which relay(s) should operate corresponding breakers.



Select one or more:

- \Box a. $R_{CB'}$ R_{CA}
- ✓ b. R_{BC}, R_{CB}
- \Box c. $R_{BC'}R_{BA}$
- $\ \ \, \square \ \, \text{d.} \, \, \text{R}_{\text{AB'}} \, \, \text{R}_{\text{CB}}$

Question 7

Answer saved

Marked out of 2

Which of the following provides the correct information for directionalovercurrent relay experiment performed as in the laboratory?


- a. Relay requires 220 V AC supply as input, but the trip coil does not require any supply for opening the breaker contact
- b. Phase angle of current signal is varied considering voltage signal as reference
- c. Phase angles of voltage and current signals are varied simultaneously
- d. Phase angle of voltage signal is varied considering current signal as reference with magnitude set above its pickup setting



Answer saved

Marked out of 2

A directional overcurrent relay is set with a characteristic as shown below. The nominal current is 10 A and the pickup setting is 0.3 times of nominal current. For which of the following situations, the relay will generate trip signal



- \Box a. Fault current = 2.5 A, angle between voltage and current is 120 $^{\circ}$
- \Box b. Fault current = 4.2 A, angle between voltage and current is 83 $^{\circ}$
- \Box c. Fault current = 1.9 A, angle between voltage and current is -5 0
- \checkmark d. Fault current = 3.8 A, angle between voltage and current is 85 0




Answer saved

Marked out of 2

A directional overcurrent relay is set with a characteristic as shown below.

The relay decision observed in the experiment are provided below. What are the most suitable values for β and γ ?



Angle (V-I) (deg)	1	15	27	42	64	86	99	127	134	138	148	156	164	178
Trip/ No trip (relay decision)	Trlp	Trlp	Trip	Trip	Trip	Trip	Trip	Trlp	No trip					
Angle (V-I) (deg)	-6	-18	-28	-39	-43	-46	-58	-71	- 82	-105	·125	-154	-170	-176
Trip/ No trip (relay decision)	Trip	Trip	Trip	Trip	Trip	Trip	No trip							

$$\triangle$$
 a. β = 130°, γ = -50°

$$\Box$$
 b. β = 170⁰, γ = -10⁰

$$\Box$$
 c. $\beta = 135^0$, $\gamma = -45^0$

$$\Box$$
 d. $\beta = 90^{\circ}$, $\gamma = -90^{\circ}$



Answer saved

Marked out of 2

In the directional-overcurrent relay experiment, the relay is set with β =1450 and γ =-350 and pickup current = 0.3 kA. What will be the relay decision for following two cases of three phase fault?

Case-1 Case-2

Select one or more:

- ✓ a. Case-1: Trip, Case-2: No Trip
- ☐ b. Case-1: No Trip, Case-2: No Trip
- c. Case-1: Trip, Case-2: Trip
- ☐ d. Case-1: No Trip, Case-2: Trip

Question 11

Answer saved

Marked out of 2

A transformer differential relay observes the presence of 2nd and 5th harmonic components as (9% and 41%) respectively of the fundamental component in the differential current. Such a situation indicates which of the following situation?

Select one or more:

- a. CT saturation
- ☐ b. Inrush
- c. High loading
- d. Overexcitation

Question 12

Answer saved

Marked out of 2

The percentage biased differential characteristic for transformer protection

- ✓ a. considers higher slope for higher restraint current
- ☐ b. uses only primary current when the secondary side CT saturates
- c. uses differential current of 5th harmonic
- ☐ d. does not consider magnetizing current



Question 13 Answer saved	Which of the following is not considered for percentage biased differential relay setting for transformer
Marked out of 2	Select one or more:
	✓ a. CT saturation
	✓ b. CT ratio error
	☐ c. Magnetizing current
	d. Maximum fault resistance
Question 14	Which of the following is not correct regarding transformer differential relay
Answer saved	experiment?
Marked out of 2	Select one or more:
	a. 2 nd harmonic blocking is required to avoid false tripping during energization
	b. High differential current is required to trip the relay in higher loading condition
	c. Relay sensitivity increases with higher bias setting
	d. Differential current increases with lower fault resistance
Question 15	Which of the following harmonic component becomes the most dominant in
Answer saved	case of transformer inrush situation?
Marked out of 2	Select one or more:
	□ a. 3 rd
	✓ b. 4 th
	c.5 th

GET IN TOUCH WITH US

Q Address : Ground floor of Kalidas Auditorium, IIT Khargpur 721302

d. 2nd

Email: moodle.helpdeskiitkgp@gmail.com

L Desk Phone : +91 (03222) 281 070/072



Moodle is a highly flexible open-source learning platform, with complete, customization and secure learning management features to create a private website filled with dynamic courses that extend elearning education anytime, anywhere.

Copyright © 2021 IIT Kharagpur

