

Feeder Reliability Summary — feeder-017-0078

Reliability summary for feeder feeder-017-0078, a 25.0 kV distribution circuit rated 535 A, served from substation sub-ramirezstad-017 in the Pacific region. Current feeder status: energized.

Customer base: this feeder serves 0 metered service points — . Only active and inactive meters count toward customers-affected figures in reliability reporting; disconnected services are excluded.

Outage history over the trailing twelve months: 3 recorded events (P3: 3). Average restoration time was 146 minutes across 3 restored events, for a total of approximately 1,000,679 customer-minutes of interruption on this feeder.

Cause breakdown: unknown — 1 event(s); vegetation contact — 1 event(s); overload — 1 event(s). No single failure mode dominates this feeder's outage history.