

Outage Post-Mortem Report — Outage #27

Outage #27 was recorded on feeder feeder-025-0048 (served from substation sub-jasonfort-025, Southwest region) beginning 2026-06-28 at 19:34 UTC. The event was classified severity P2 and affected approximately 2235 customers. Reported cause: vehicle accident.

Service was restored at 2026-06-29 00:02 UTC, giving a total restoration time of 268 minutes. This exceeded the P2 target restoration window and was flagged for reliability review.

Crew response: Crew Golf was dispatched at 2025-12-07 04:30 UTC with a recorded response time of 139 minutes to on-site arrival. Response time is logged for trending against severity targets.

Root cause summary: Vehicle accident on Julie Centers feeder segment; restored via manual crew switching.

Corrective actions: this feeder has been added to the worst-performing-feeder watch list for the current reporting year.