

Outage Post-Mortem Report — Outage #185

Outage #185 was recorded on feeder feeder-036-0006 (served from substation sub-southaaron-036, Pacific region) beginning 2026-05-06 at 08:37 UTC. The event was classified severity P2 and affected approximately 3780 customers. Reported cause: storm damage.

Service was restored at 2026-05-06 12:53 UTC, giving a total restoration time of 256 minutes. This exceeded the P2 target restoration window and was flagged for reliability review.

Crew response: Crew Golf was dispatched at 2026-08-02 04:51 UTC with a recorded response time of 69 minutes to on-site arrival. Response time is logged for trending against severity targets.

Root cause summary: Storm damage on Julia Track feeder segment; restored via automatic reclose.

Corrective actions: no corrective action beyond standard repair was identified; the event is considered closed.