

Outage Post-Mortem Report — Outage #257

Outage #257 was recorded on feeder feeder-016-0364 (served from substation sub-portjesseville-016, Southwest region) beginning 2026-02-04 at 02:13 UTC. The event was classified severity P2 and affected approximately 2385 customers. Reported cause: storm damage.

Service was restored at 2026-02-04 06:28 UTC, giving a total restoration time of 255 minutes. This exceeded the P2 target restoration window and was flagged for reliability review.

Crew response: Crew Foxtrot was dispatched at 2026-05-07 21:04 UTC with a recorded response time of 167 minutes to on-site arrival. Response time is logged for trending against severity targets.

Root cause summary: Storm damage on Reed Plaza feeder segment; restored via manual crew switching.

Corrective actions: no corrective action beyond standard repair was identified; the event is considered closed.