

Outage Post-Mortem Report — Outage #349

Outage #349 was recorded on feeder feeder-019-0181 (served from substation sub-jacquelineland-019, Northeast region) beginning 2026-03-11 at 02:01 UTC. The event was classified severity P2 and affected approximately 2732 customers. Reported cause: planned maintenance.

As of this report, outage #349 remains open with no restoration timestamp recorded. Restoration status should be confirmed with the control center.

Crew response: Crew Juliet was dispatched at 2026-05-10 23:27 UTC with a recorded response time of 6 minutes to on-site arrival. Response time is logged for trending against severity targets.

Root cause summary: Planned maintenance on Fox Summit feeder segment; restored via automatic reclose.

Corrective actions: vegetation management cycle for this feeder segment has been advanced to the next available crew window.