

Transformer Inspection Report — XFMR-00206

Asset inspection record for transformer XFMR-00206, a 39.97 MVA unit manufactured by Schneider Electric and installed in 1986 (40 years in service). The unit is connected to feeder feeder-007-0138 at substation sub-lisatown-007 and its current status is de-energized.

Visual inspection findings: oil level and condition — darkened — schedule dielectric test. Bushings — light corrosion at flange. Cooling fans and radiators were cycling correctly under load. Grounding connections were verified intact. Inspection performed by a Relay Technician under weather conditions: extreme heat advisory.

SCADA alarm history for XFMR-00206 over the trailing twelve months shows 3 recorded alarms: breaker trip (2), low oil level (1). 2 of these remain unresolved.

Thermal alarm count (0) is below the capacity-upgrade-review threshold. No loading study is required at this time.

Recommended follow-up: unit is de-energized; confirm clearance and tagout status before any further work.