

Transformer Inspection Report — XFMR-00343

Asset inspection record for transformer XFMR-00343, a 31.37 MVA unit manufactured by Hitachi Energy and installed in 2000 (26 years in service). The unit is connected to feeder feeder-024-0187 at substation sub-adamsborough-024 and its current status is in_service.

Visual inspection findings: oil level and condition — darkened — schedule dielectric test. Bushings — clean, gasket intact. Cooling fans and radiators were operating normally with minor debris accumulation. Grounding connections were verified intact. Inspection performed by a Substation Technician under weather conditions: extreme heat advisory.

SCADA alarm history for XFMR-00343 over the trailing twelve months shows 2 recorded alarms: communication loss (1), differential protection trip (1). 0 of these remain unresolved.

Thermal alarm count (0) is below the capacity-upgrade-review threshold. No loading study is required at this time.

Recommended follow-up: re-inspect at the standard interval; no defects requiring intervention were found.