
EAST CENTRAL RAILWAY



Office of the Sr. DEE/MEMU/Jhajha Date- 26.11.2024

Dy. CEE/W Eastern Railway Kanchrapara.

Sub: Request for attention to defects found in power cables during Scheduled Inspection of MEMU MC

This is to bring to your kind attention that the MEMU rake with formation 198959+048024+178305+198890 was scheduled for inspection on 26th November 2024 at MEMU Shed, Jhajha. During the scheduled inspection, defects were identified in MEMU MC 048024, as outlined below in

SN	MC No.	Last POH	Defect found.
	048024	NOV 23	i) The M6 and M8 power cables on the JB2 (MCP side) were heated &
			power cable serving, armouring & insulation found cut/damage.
			ii) Four M8 cables in JB2 are exhibiting bulging.
			iii) Oil leakage is occurring at the M1 and M8 terminal bars. Additionally, oil leakage is observed from the M2 terminal bar on JB1 (Rectifier side), with slight oil leakage also noted from the Auxiliary JB.

Hence, it is requested that your representative be deputed with the required material to address the defects at the earliest. This matter is requested to give your prompt attention, and your necessary action is awaited to resolve the issues mentioned above. The images are attached as Annexure A below this

This is for your kind information and necessary action please.

Sr. DEE/MEMU/JAJ E.C.Railway, Danapur

Copy to:-

CESE/ECR/HJP : For kind information please.

Annexure A.





