## **Fire Prevention Measures in EMU MEMU**

1.	Provision of temper checker marker on nut and bolt of power cable terminal after tightening with adequate torque
2.	Transparent heat shrinkable sleeve at crimping area of power cable lug
3.	Irreversible thermal strips at power cable terminals
4.	Borescopes/endoscope to see condition of Power cable in Junction boxes
5.	Thermal imaging of cable as per RDSO maintenance schedules to identify pattern of loose connections flashing etc and ensure tightness,
6.	Ensuring tightness of loose cable connections in power and control circuits
7.	Checking of condition of power and control cables and change on condition basis
8.	Modification in Transformer oil pipeline arrangement on rectifier side to improve accessibility to Transformer cable J2 junction box
9.	Shifting of pneumatic pipeline of Air suspension and parking Brake to ease inspection of J2 Junction box
10.	Modification of dimensions of 125 L Air reservoir in front of Transformer cable J1 junction box to improve accessibility to the same
11.	Removal of Rectifier assembly to check power cables
12.	Retro fitment of Aerosol based fire suppression system
13.	Retro fitment of fire detection system
14.	Provision of Fire detection system and Aerosol based fire suppression system in the rakes turned out from PUs.
	•