

ZOOM ® View™ Report Created 17 Mar 2017

**QUICK NOTES ® Report** 

Date of Birth N/R N/R N/R

Device VALITUDE X4 U128/705938

Last Office Interrogation

20 Oct 2016 Implant Date N/R

My Alerts

📤 17 Mar 2017 15:20 Check Atrial Lead

**Events Since Last Reset (09 May 2016)** 

23 Oct 2016 23:46 NonSustV at 190 min<sup>-1</sup>
17 Jun 2016 23:39 NonSustV at 159 min<sup>-1</sup>
See last page for full list of Events Since Last Reset.

Battery OK

Approximate time to explant: 6.5 years Magnet Rate 100 min<sup>-1</sup>

One Year Remaining Explant

		Explain -	Explain .	
Leads Data	<b>Implant</b> N/R N/R N/R	Previous Session	Most Recent	
Atrial				
Intrinsic Amplitude	N/R mV	N/R mV	N/R mV	
Pace Impedance	N/R Ω	>3000 Ω	>3000 Ω	
Pace Threshold	N/R V @ N/R ms	Test Failed	No data collected	
Right Ventricular				
Intrinsic Amplitude	N/R mV	15.4 mV	14.0 mV @ 91 min <sup>-1</sup>	
Pace Impedance	N/R $\Omega$	790 Ω	708 Ω	
Pace Threshold	N/R V @ N/R ms	0.9 V @ 0.4 ms	0.6 V @ 0.4 ms	
Left Ventricular				
Intrinsic Amplitude	N/R mV	19.2 mV	23.5 mV	
Pace Impedance	N/R $\Omega$	1346 Ω	$905~\Omega$	
Pace Threshold	N/R V @ N/R ms	5.5 V @ 0.6 ms	1.4 V @ 1.4 ms	
Brady/CRT Counters Since Las	t Reset (09 May 2016)			

Brady/CRT Counters Since Last Reset (09 May 2016)

Counters

Atrial 100% Paced
Right Ventricular 98% Paced
Left Ventricular 98% Paced

**Atrial Arrhythmia** 

% AT/AF 0

Settings

**Ventricular Tachy Settings** 

Ventricular Tachy EGM Storage On
Detection Rate 160 min<sup>-1</sup>

**Brady/CRT Settings** 

Mode VVIR Pacing Output Lower Rate Limit 85 min<sup>-1</sup> Right Ventricular

Lower Rate Limit

85 min<sup>-1</sup>

Right Ventricular

Trend 3.0 V @ 0.4 ms

Maximum Sensor Rate

130 min<sup>-1</sup>

RUPROFINATION Sensitivity

Sensitivity

Atrial

Fixed 0.75 mV

LV-Refractory (LVRP)250 msAtrialFixed 0.75 mVVentricular Pacing ChamberBiVRight VentricularFixed 2.5 mVLV Offset-30 msLeft VentricularFixed 2.5 mV

LV Offset -30 ms Left Ventricular
Leads Configuration (Pace/Sense)

Atrial --/Off Right Ventricular Bipolar

2869 Software Version: 2.02 U128 Firmware Version: F\_v1.00.00 © 2014

Boston Scientific Corporation or its affiliates. All rights reserved.

Page 1 of 2

Clinician Signature:

## **Settings (Continued)**

**Brady/CRT Settings** 

Leads Configuration (Pace/Sense)

LV (Pace) LV (Sense) LVTip1>>Can LVTip1>>LVRing2

## All Events Since Last Reset (09 May 2016)

17 Mar 2017 08:44 RV Auto

23 Oct 2016 23:46 NonSustV at 190 min<sup>-1</sup>
17 Jun 2016 23:39 NonSustV at 159 min<sup>-1</sup>
13 May 2016 20:17 NonSustV at 168 min<sup>-1</sup>

Clinician Signature: