

ZOOM ® View™ Report Created 10 Jun 2019

QUICK NOTES ® Report

Hucík, Stepán

Date of Birth

Device

7 Jan 1944

INCEPTA CRT-D P162/119874

Tachy Mode Monitor + Therapy

Last Office Interrogation

02 May 2019 Implant Date **12 Mar 2013**

My Alerts

▲ 10 Jun 2019 11:06 Check Atrial and LV Leads

Events Since Last Reset (04 Jun 2018)

07 Mar 2019 21:06 NonSustV at 159 min⁻¹, Nonsustained 30 Nov 2018 10:37 NonSustV at 136 min⁻¹, Nonsustained

See last page for full list of Events Since Last Reset.

Battery OK

Approximate time to explant: 2.5 years
Charge Time 11.3 s
Last Capacitor Re-form 28 Apr 2019 09:28

One Year Remaining

Explant

Leads Data	Implant 12 Mar 2013	Previous Session	Most Recent
Atrial			
Intrinsic Amplitude	N/R mV	N/R mV	N/R mV
Pace Impedance	N/R Ω	>2500 Ω	<200 Ω
Pace Threshold	N/R V @ N/R ms	4.0 V @ 0.4 ms	
Right Ventricular			
Intrinsic Amplitude	7.0 mV	6.0 mV	N/R mV @ N/R min ⁻¹
Pace Impedance	$650~\Omega$	507 Ω	495 Ω
Pace Threshold	0.5 V @ 0.4 ms	1.1 V @ 0.4 ms	
Left Ventricular			
Intrinsic Amplitude	12.0 mV	20.7 mV	N/R mV
Pace Impedance	$650~\Omega$	545 Ω	494 Ω
Pace Threshold	1.3 V @ 0.4 ms	1.2 V @ 0.4 ms	
Shock Vector			
Shock Impedance	45 Ω	56 Ω	52 Ω
Dua de JODE Carratana Cinas I as	(D (/0.4 L 00.40)		

Brady/CRT Counters Since Last Reset (04 Jun 2018)

Counters

Atrial 0% Paced Right Ventricular 93% Paced Left Ventricular 100% Paced

Atrial Arrhythmia

% AT/AF 0

(One Year of Data)

Settings

Ventricular Tachy Settings

VF 230 min⁻¹ ATP 31J, 41J, 41Jx6 VT 205 min⁻¹ Scan Ramp 31J, 41J, 41Jx4 VT-1 160 min⁻¹ Scan Ramp 41J, 41J, 41Jx3

Brady/CRT Settings

Mode **VVIR Pacing Output** Lower Rate Limit 65 min⁻¹ Right Ventricular 2.5 V @ 0.4 ms Maximum Sensor Rate 130 min⁻¹ Left Ventricular 3.0 V @ 0.4 ms 230 - 250 ms RV-Refractory (RVRP) Sensitivity LV-Refractory (LVRP) 250 ms AGC 0.25 mV Atrial Ventricular Pacing Chamber BiV Right Ventricular AGC 0.6 mV

2868 Software Version: 4.07

P162 Firmware Version: B_v1.02.00(4.01)

© 2016

Boston Scientific Corporation or its affiliates. All rights reserved.

Page 1 of 2

Clinician Signature:

Settings (Continued)

Brady/CRT Settings

LV Offset 0 ms Sensitivity

Left Ventricular AGC 1.0 mV

Leads Configuration (Pace/Sense)

Atrial Bipolar/Off
Right Ventricular Bipolar
Left Ventricular LVring>>RV / LVtip>>LVring

All Events Since Last Reset (04 Jun 2018)

07 Mar 2019 21:06	NonSustV at 159 min ⁻¹ , Nonsustained
30 Nov 2018 10:37	NonSustV at 136 min ⁻¹ , Nonsustained
05 Nov 2018 13:35	NonSustV at 143 min ⁻¹ , Nonsustained
25 Oct 2018 00:58	NonSustV at 128 min ⁻¹ , Nonsustained
02 Sep 2018 05:41	NonSustV at 163 min ⁻¹ , Nonsustained
03 Aug 2018 22:41	NonSustV at 145 min ⁻¹ , Nonsustained
02 Aug 2018 20:20	NonSustV at 171 min ⁻¹ , Nonsustained
25 Jul 2018 17:13	NonSustV at 166 min ⁻¹ , Nonsustained
24 Jul 2018 12:34	NonSustV at 154 min ⁻¹ Nonsustained

2868 Software Version: 4.07

P162 Firmware Version: B_v1.02.00(4.01)

© 2016

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 2 of 2

Clinician Signature: