

LATITUDE™ Programming System

All Episodes Report

Krajca 540702, Miroslav

Date of Birth
Device

CHARISMA CRT-D G324/ 500899

Report Created 23 Feb 2022

Last Office Interrogation
22 Feb 2022

Implant Date

Event SAM-1: 23 Feb 2022 07:27

25mm/s

22 Feb 2022

The Respiratory Sensor vector was switched by the Signal Artifact Monitor.

Sensor vector with failed sensor lead check	Α
Excitation Level	320 µA

Tachy Mode

Impedances at the time of failed sensor lead check


• A Pace Impedance >3000 Ω ■ RV Pace Impedance 667 Ω

Event Ended -----



Monitor + Therapy

Clinician Signature:



	D	IVD	LVD	IVD	
LV 78	ნ	780	LVP 780	LVP 780	
R\ 80	/P	RVP 800	RVP 800	RVP 800	
80	10	800	800	800	

