Scientific Scientific

System Fault Warning

Date of Birth N/R N/R N/R

ZOOM ® ViewTM

Tachy Mode Off

Device

TELIGEN 100 F110/005745 Implant Date Last Office Interrogation 31 Aug 2015

Report Created 04 Feb 2019

Warning Details

Voltage is too low for projected remaining capacity.

Contact Technical Services with code 1003

1-800-CARDIAC (North America) or contact your local Boston Scientific representative.

2868 Software Version: 4.06 F110 Firmware

Version: A_v1.04.0(5.01)

© 2016

Boston Scientific Corporation or its affiliates. All rights reserved.

Page 1 of 1

Clinician Signature: