

ZOOM ® View<sup>™</sup> Report Created 08 Jan 2018

**QUICK NOTES ® Report** 

Date of Birth N/R N/R N/R

Device VITALIO MRI J275/101893

Last Office Interrogation

09 Jan 2017 Implant Date N/R

My Alerts

**a** 08 Jan 2018 10:40 Check Lead

**Events Since Last Reset (02 Jun 2014)** 

14 Dec 2017 11:09 Tachy at 177 min<sup>-1</sup>
14 Dec 2017 11:08 Tachy at 181 min<sup>-1</sup>
See last page for full list of Events Since Last Reset.

Battery OK

Approximate time to explant: 8.5 years
Magnet Rate 100 min<sup>-1</sup>

Explant

**One Year Remaining** 

**Leads Data Implant Previous Session Most Recent** N/R N/R N/R Intrinsic Amplitude N/R mV >25.0 mV 20.5 mV @ 39 min<sup>-1</sup> Pace Impedance  $N/R \Omega$ 588 Ω 576 Ω Pace Threshold N/R V @ N/R ms 0.6 V @ 0.4 ms Auto 1.0 V @ 0.4 ms

**Brady Counters Since Last Reset (02 Jun 2014)** 

Counters

% Paced 52

Settings

**Tachy Settings**Tachy EGM Storage On

Detection Rate 160 min<sup>-1</sup>

**Brady Settings** 

Mode VVIR Pacing Output

Lower Rate Limit 55 min<sup>-1</sup>

Maximum Sensor Rate 115 min<sup>-1</sup> Sensitivity

Refractory 250 - 250 ms Fixed 2.0 mV

Leads Configuration (Pace/Sense)

Unipolar/Bipolar

Auto 1.5 V @ 0.4 ms

## All Events Since Last Reset (02 Jun 2014)

04 Jan 2018 16:20	NonSust at 134 min <sup>-1</sup>
29 Dec 2017 13:05	NonSust at 137 min <sup>-1</sup>
29 Dec 2017 12:59	NonSust at 151 min <sup>-1</sup>
29 Dec 2017 12:56	NonSust at 141 min <sup>-1</sup>
29 Dec 2017 12:55	NonSust at 141 min <sup>-1</sup>
29 Dec 2017 12:55	NonSust at 141 min <sup>-1</sup>
29 Dec 2017 12:54	NonSust at 137 min <sup>-1</sup>
29 Dec 2017 12:54	NonSust at 194 min <sup>-1</sup>
29 Dec 2017 12:53	NonSust at 152 min <sup>-1</sup>
29 Dec 2017 12:53	NonSust at 157 min <sup>-1</sup>
14 Dec 2017 11:09	Tachy at 177 min <sup>-1</sup>
14 Dec 2017 11:08	Tachy at 181 min <sup>-1</sup>
14 Dec 2017 11:07	Tachy at 186 min <sup>-1</sup>
14 Dec 2017 11:06	Tachy at 180 min <sup>-1</sup>
14 Dec 2017 11:05	Tachy at 166 min <sup>-1</sup>
14 Dec 2017 11:03	Tachy at 186 min⁻¹

2869 Software Version: 2.02

J275 Firmware Version: D\_v1.02.00(1.01)

© 2014

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 1 of 2

Clinician Signature:

Events Since	Last Reset	(Continued)	(02 Jun 2
14 Dec 2017 1	11:02	Tachy at 1	74 min <sup>-1</sup>
14 Dec 2017 1	11:02	Tachy at 1	47 min <sup>-1</sup>
14 Dec 2017 1	10:55	Tachy at 1	82 min <sup>-1</sup>
14 Dec 2017 1	10:49	Tachy at 1	68 min <sup>-1</sup>
13 Dec 2017 0	08:12	Tachy at 1	74 min <sup>-1</sup>
30 Nov 2017 1	15:03	Tachy at 1	68 min <sup>-1</sup>
30 Nov 2017 1	15:02	Tachy at 1	80 min <sup>-1</sup>
30 Nov 2017 1	15:01	Tachy at 1	66 min <sup>-1</sup>
30 Nov 2017 1	14:59	Tachy at 1	72 min <sup>-1</sup>
30 Nov 2017 1	14:56	Tachy at 1	72 min <sup>-1</sup>
30 Nov 2017 1	14:52	Tachy at 1	72 min <sup>-1</sup>
30 Nov 2017 1	14:48	Tachy at 1	75 min <sup>-1</sup>
30 Nov 2017 1	14:42	Tachy at 1	
28 Nov 2017 1	18:22	Tachy at 1	
13 Nov 2017 0		Tachy at 1	
12 Nov 2017 0		Tachy at 1	
12 Nov 2017 0		Tachy at 1	
12 Nov 2017 0		Tachy at 1	
12 Nov 2017 0		Tachy at 1	
09 Nov 2017 2		Tachy at 1	
06 Nov 2017 2		Tachy at 1	
06 Nov 2017 1		Tachy at 1	
06 Nov 2017 1		Tachy at 1	
06 Nov 2017 1		Tachy at 1	
06 Nov 2017 1		Tachy at 1	
12 Oct 2017 0		Tachy at 1	
12 Oct 2017 0		Tachy at 1	
12 Oct 2017 0		Tachy at 1	
12 Oct 2017 0		Tachy at 1	
12 Oct 2017 0		Tachy at 1	
12 Oct 2017 0		Tachy at 1	
12 Oct 2017 0 12 Oct 2017 0		Tachy at 1 Tachy at 1	
12 Oct 2017 0		•	
12 Oct 2017 0		Tachy at 1	
12 Oct 2017 0		Tachy at 1 Tachy at 1	
10 Oct 2017 0		Tachy at 1	
14 Sep 2017 1		Tachy at 1	
12 Sep 2017 1		Tachy at 1	
24 Aug 2017 1		Tachy at 1	
24 Aug 2017 1		Tachy at 1	
24 Aug 2017 1		Tachy at 1	
24 Aug 2017 1		Tachy at 1	
23 Jul 2017 08		Tachy at 1	
26 Jan 2015 1		RV Auto	
_0 04.1 _0 10 1		/	

2869 Software Version: 2.02 J275 Firmware Version: D\_v1.02.00(1.01)

Clinician Signature: