

ZOOM ® View™ Report Created 27 Jun 2016 **QUICK NOTES ® Report**

KRÍZ, Karel

Date of Birth 30 Aug 1954

AUTOĞEN X4 CRT-D G179/136339 Device Monitor + Therapy Tachy Mode

Last Office Interrogation

03 Jun 2016 Implant Date 12 Oct 2015

My Alerts

24 Jun 2016 08:54 Atrial Tachycardia Response (ATR) detected for >48 hours.

27 Jun 2016 11:25 Check LV Lead

Events Since Last Reset (02 Jun 2016)

VF at 268 min⁻¹, No Therapy 04 Jun 2016 19:32 VF at 262 min⁻¹, No Therapy 04 Jun 2016 19:21 See last page for full list of Events Since Last Reset.

Battery OK

> Approximate time to explant: 8 years Charge Time 9.5 sLast Capacitor Re-form

20 Jan 2016 10:08



Leads Data	Implant 12 Oct 2015	Previous Session	Most Recent	
Atrial				
Intrinsic Amplitude	N/R mV	5.1 mV	2.8 mV	
Pace Impedance	N/R Ω	$786~\Omega$	855 Ω	
Pace Threshold	N/R V @ N/R ms	1.0 V @ 0.4 ms	No data collected	
Right Ventricular				
Intrinsic Amplitude	N/R mV	10.3 mV	10.1 mV @ 50 min ⁻¹	
Pace Impedance	N/R Ω	$355~\Omega$	424 Ω	
Pace Threshold	N/R V @ N/R ms	1.1 V @ 0.4 ms	1.1 V @ 0.4 ms	
Left Ventricular				
Intrinsic Amplitude	N/R mV	7.5 mV	4.2 mV	
Pace Impedance	N/R Ω	$603~\Omega$	705 Ω	
Pace Threshold	N/R V @ N/R ms	1.1 V @ 0.4 ms	1.0 V @ 0.4 ms	
Shock Vector				
Shock Impedance	N/R Ω	53 Ω	55 Ω	
Brady/CRT Counters Since Last Reset (02 Jun 2016)				

Brady/CRT Counters Since Last Reset (02 Jun 2016)

Atrial 2% Paced Right Ventricular 78% Paced Left Ventricular 95% Paced

Settings

Atrial Tachy Settings Ventricular Tachy Settings VF 230 min⁻¹ ATP 36J, 41J, 41Jx6 ATR Mode Switch 170 min⁻¹ DDI VT 185 min⁻¹ Burst Ramp 31J, 36J, 41Jx4

Brady/CRT Settings

Mode	DDDR	Pacing Output	
Lower Rate Limit	85 min ⁻¹	Atrial	2.5 V @ 0.4 ms
Maximum Tracking Rate	130 min ⁻¹	Right Ventricular	3.0 V @ 0.4 ms
Maximum Sensor Rate	130 min ⁻¹	Left Ventricular	3.5 V @ 0.4 ms
Paced AV Delay	220 - 250 ms	Sensitivity	
Sensed AV Delay	165 - 190 ms	Atrial	AGC 0.25 mV
A-Refractory (PVARP)	240 - 280 ms	Right Ventricular	AGC 0.6 mV
RV-Refractory (RVRP)	230 - 250 ms	Left Ventricular	AGC 1.0 mV
LV-Refractory (LVRP)	250 ms	Leads Configuration (Pace/Sense)	
Ventricular Pacing Chamber	BiV	Atrial	Bipolar

2868 Software Version: 3.07

Boston Scientific Corporation G179 Firmware Version: E_v1.02.00(2.01) Page 1 of 2

© 2014 or its affiliates. All rights reserved.

Clinician Signature:

Settings (Continued) Brady/CRT Settings

LV Offset -60 ms Leads Configuration (Pace/Sense)

Right Ventricular LV (Pace)

LV (Sense)

Bipolar LVRing3>>Can LVTip1>>LVRing2

All Events Since Last Reset (02 Jun 2016)

ATR at 194 min ⁻¹ , Avg V Rate in ATR: 0 min ⁻¹
ATR at 192 min ⁻¹ , Avg V Rate in ATR: 95 min ⁻¹
ATR at 194 min ⁻¹ , Avg V Rate in ATR: 95 min ⁻¹
ATR at 197 min ⁻¹ , Avg V Rate in ATR: 76 min ⁻¹
ATR at 194 min ⁻¹ , Avg V Rate in ATR: 79 min ⁻¹
ATR at 192 min ⁻¹ , Avg V Rate in ATR: 95 min ⁻¹
ATR at 194 min ⁻¹ , Avg V Rate in ATR: 72 min ⁻¹
ATR at 188 min ⁻¹ , Avg V Rate in ATR: 85 min ⁻¹
ATR at 186 min ⁻¹ , Avg V Rate in ATR: 93 min ⁻¹
ATR at 204 min ⁻¹ , Avg V Rate in ATR: 72 min ⁻¹
ATR at 202 min ⁻¹ , Avg V Rate in ATR: 100 min ⁻¹
ATR at 190 min ⁻¹ , Avg V Rate in ATR: 87 min ⁻¹
ATR at 189 min ⁻¹ , Avg V Rate in ATR: 93 min ⁻¹
ATR at 189 min ⁻¹ , Avg V Rate in ATR: 94 min ⁻¹
PMT at 130 min ⁻¹
PMT at 130 min ⁻¹
PMT at 130 min ⁻¹
PMT at 130 min ⁻¹
PMT at 130 min ⁻¹
VF at 268 min ⁻¹ , No Therapy
VF at 262 min ⁻¹ , No Therapy

2868 Software Version: 3.07 G179 Firmware Version: E_v1.02.00(2.01) © 2014

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 2 of 2

Clinician Signature: