

LATITUDE™ Programming System Report Created 23 Feb 2022 **QUICK NOTES ® Report** 

Krajca 540702, Miroslav Date of Birth N/R N/R N/R

CHARISMA CRT-D G324/500899 Device Tachy Mode Monitor + Therapy

Last Office Interrogation 22 Feb 2022

Implant Date 22 Feb 2022

My Alerts

There are no alerts to display.

Events Since Last Reset (22 Feb 2022)

SAM, Respiratory Sensor Vector Switched 23 Feb 2022 07:27

LV Auto 22 Feb 2022 12:30 22 Feb 2022 12:28 **RV** Auto

**Battery** OK

> Approximate time to explant: > 8 years Charge Time N/Rs N/R

Last Capacitor Re-form



Leads Data	<b>Implant</b> 22 Feb 2022	Previous Session	Most Recent
Atrial			
Intrinsic Amplitude	N/R mV	0.5 mV	N/R mV
Pace Impedance	N/R Ω	>3000 Ω	>3000 Ω
Pace Threshold	N/R V @ N/R ms	N/R	Test Failed
Right Ventricular			
Intrinsic Amplitude	N/R mV	Paced mV	>25.0 mV @ 48 min <sup>-1</sup>
Pace Impedance	N/R Ω	634 Ω	669 Ω
Pace Threshold	N/R V @ N/R ms	Auto 0.8 V @ 0.4 ms	Auto 0.8 V @ 0.4 ms
Left Ventricular			
Intrinsic Amplitude	N/R mV	Paced mV	4.9 mV
Pace Impedance	N/R Ω	654 Ω	706 Ω
Pace Threshold	N/R V @ N/R ms	Auto 2.5 V @ 1.0 ms	Auto 2.2 V @ 1.0 ms
Shock Vector			
Shock Impedance	N/R Ω	58 Ω	58 Ω
d. /CDT C C L L D	. 1 /00 E . L 0000)		

Brady/CRT Counters Since Last Reset (22 Feb 2022)

Counters

0% Paced Atrial Right Ventricular 100% Paced Left Ventricular 100% Paced

Atrial Arrhythmia

% AT/AF N/R Settings

**Ventricular Tachy Settings** 

200 min<sup>-1</sup> ATP 41J, 41J, 41Jx6 VF 165 min⁻¹ Burst VT 41J, 41J, 41Jx4 Ramp

**Brady/CRT Settings** 

**VVIR** Pacing Output Mode Lower Rate Limit 75 min<sup>-1</sup> Right Ventricular Auto 2.0 V @ 0.4ms Maximum Sensor Rate 130 min<sup>-1</sup> Left Ventricular Auto 3.2 V @ 1.0ms RV-Refractory (RVRP) 230 - 250 ms Sensitivity

LV-Refractory (LVRP) Atrial AGC 0.25 mV 250 ms Ventricular Pacing Chamber Right Ventricular AGC 0.6 mV BiV LV Offset Left Ventricular AGC 1.0 mV -20 ms

Leads Configuration (Pace/Sense)

Atrial Bipolar Right Ventricular Bipolar Left Ventricular LVtip>>Can / LVtip>>LVring

3868 Software Version: 1.10 G324 Firmware Version: H\_v1.00.00(1.01)

© 2014-2019 **Boston Scientific Corporation** or its affiliates. All rights reserved. Page 1 of 1

Clinician Signature: