

ZOOM ® View™ Report Created 14 Feb 2022

QUICK NOTES ® Report

Hucík, Stepán

Date of Birth

Device

7 Jan 1944

INCEPTA CRT-D P162/119874

Tachy Mode Monitor + Therapy Last Office Interrogation

13 Sep 2021 Implant Date 12 Mar 2013

My Alerts

30 Dec 2021 Explant indicator reached A 14 Feb 2022 10:24 Check Atrial and LV Leads

Events Since Last Reset (03 May 2021)

NonSustV at 177 min⁻¹, Nonsustained 02 Jan 2022 22:31 NonSustV at 153 min⁻¹, Nonsustained 28 Dec 2021 16:10

See last page for full list of Events Since Last Reset.

Battery

Explant indicator reached on 30 Dec 2021 Charge Time 15.4 s

Last Capacitor Re-form 30 Dec 2021 11:42



Leads Data	Implant 12 Mar 2013	Previous Session	Most Recent
Atrial			
Intrinsic Amplitude	N/R mV	N/R mV	N/R mV
Pace Impedance	N/R Ω	>2500 Ω	>2500 Ω
Pace Threshold	N/R V @ N/R ms	4.0 V @ 0.4 ms	
Right Ventricular			
Intrinsic Amplitude	7.0 mV	8.3 mV	9.5 mV @ 51 min ⁻¹
Pace Impedance	$650~\Omega$	467 Ω	473 Ω
Pace Threshold	0.5 V @ 0.4 ms	0.9 V @ 0.4 ms	
Left Ventricular			
Intrinsic Amplitude	12.0 mV	21.2 mV	19.9 mV
Pace Impedance	$650~\Omega$	584 Ω	592 Ω
Pace Threshold	1.3 V @ 0.4 ms	2.0 V @ 0.4 ms	
Shock Vector			
Shock Impedance	45 Ω	55 Ω	55 Ω
Dradu/CDT Countary Cines Lee	4 Danet (02 May 2024)		

Brady/CRT Counters Since Last Reset (03 May 2021)

Counters

Atrial 0% Paced 93% Paced Right Ventricular 100% Paced Left Ventricular

Atrial Arrhythmia

% AT/AF 0

(One Year of Data)

Settings

Ventricular Tachy Settings

31J, 41J, 41Jx6 VF 230 min⁻¹ ATP VT 205 min⁻¹ Scan Ramp 31J, 41J, 41Jx4 VT-1 160 min⁻¹ Scan Ramp 41J, 41J, 41Jx3

Brady/CRT Settings

VVIR Pacing Output Mode 65 min⁻¹ Right Ventricular Lower Rate Limit Maximum Sensor Rate 130 min⁻¹ Left Ventricular

230 - 250 ms RV-Refractory (RVRP) Sensitivity LV-Refractory (LVRP) 250 ms Atrial

AGC 0.25 mV © 2016

2868 Software Version: 4.08

Boston Scientific Corporation P162 Firmware Version: B_v1.02.00(4.01) or its affiliates. All rights reserved.

Page 1 of 2

Clinician Signature:

2.5 V @ 0.4 ms

3.5 V @ 0.4 ms

Settings (Continued)

Brady/CRT Settings

Ventricular Pacing Chamber BiV Sensitivity

LV Offset 0 ms Right Ventricular AGC 0.6 mV

Left Ventricular AGC 1.0 mV

Leads Configuration (Pace/Sense)

Atrial Bipolar/Off
Right Ventricular Bipolar
Left Ventricular LVring>>RV / LVtip>>LVring

All Events Since Last Reset (03 May 2021)

	•	,
02 Jan 2022 22:31		NonSustV at 177 min ⁻¹ , Nonsustained
28 Dec 2021 16:10		NonSustV at 153 min ⁻¹ , Nonsustained
29 Oct 2021 22:04		NonSustV at 130 min ⁻¹ , Nonsustained
28 Oct 2021 04:36		NonSustV at 153 min ⁻¹ , Nonsustained
18 Sep 2021 02:11		NonSustV at 159 min ⁻¹ , Nonsustained
16 Sep 2021 09:25		NonSustV at 163 min ⁻¹ , Nonsustained
16 Jul 2021 12:09		NonSustV at 175 min ⁻¹ , Nonsustained
12 Jun 2021 16:37		NonSustV at 127 min ⁻¹ , Nonsustained

2868 Software Version: 4.08

P162 Firmware Version: B_v1.02.00(4.01)

© 2016

Boston Scientific Corporation or its affiliates. All rights reserved.

Page 2 of 2

Clinician Signature: