

ZOOM ® View™ Report Created 08 Jun 2020

QUICK NOTES ® Report

Hucík, Stepán

Date of Birth

Device

7 Jan 1944

INCEPTA CRT-D P162/119874

Monitor + Therapy Tachy Mode

Last Office Interrogation

10 Jun 2019 Implant Date 12 Mar 2013

My Alerts

a 08 Jun 2020 10:28 Check Atrial and LV Leads

Events Since Last Reset (04 Jun 2018)

NonSustV at 163 min⁻¹, Nonsustained 26 May 2020 10:22 29 Apr 2020 05:28 NonSustV at 155 min⁻¹, Nonsustained

See last page for full list of Events Since Last Reset.

OK

Approximate time to explant: 1.5 years Charge Time 12.1 s

Last Capacitor Re-form 28 Apr 2020 08:35 **One Year Remaining Explant**

		=xpiant ·	•
Leads Data	Implant 12 Mar 2013	Previous Session	Most Recent
Atrial			
Intrinsic Amplitude	N/R mV	N/R mV	N/R mV
Pace Impedance	N/R Ω	<200 Ω	>2500 Ω
Pace Threshold	N/R V @ N/R ms	4.0 V @ 0.4 ms	
Right Ventricular			
Intrinsic Amplitude	7.0 mV	6.3 mV	8.6 mV @ 39 min ⁻¹
Pace Impedance	650 Ω	495 Ω	462 Ω
Pace Threshold	0.5 V @ 0.4 ms	1.1 V @ 0.4 ms	0.7 V @ 0.4 ms
Left Ventricular			
Intrinsic Amplitude	12.0 mV	>25.0 mV	22.0 mV
Pace Impedance	650 Ω	494 Ω	543 Ω
Pace Threshold	1.3 V @ 0.4 ms	1.2 V @ 0.4 ms	1.7 V @ 0.4 ms
Shock Vector			
Shock Impedance	45 Ω	52 Ω	52 Ω
Drady/CDT Countary Since Loc	t Docot (04 lup 2010)		

Brady/CRT Counters Since Last Reset (04 Jun 2018)

Counters

0% Paced Atrial 94% Paced Right Ventricular Left Ventricular 100% Paced

Atrial Arrhythmia

% AT/AF 0

(One Year of Data)

Settings

Ventricular Tachy Settings

VF 230 min⁻¹ ATP 31J, 41J, 41Jx6 VT 205 min⁻¹ Scan Ramp 31J, 41J, 41Jx4 VT-1 160 min⁻¹ Scan 41J, 41J, 41Jx3 Ramp

Brady/CRT Settings

Mode **VVIR Pacing Output** Lower Rate Limit 65 min⁻¹ Right Ventricular Maximum Sensor Rate 130 min⁻¹ Left Ventricular

RV-Refractory (RVRP) 230 - 250 ms Sensitivity LV-Refractory (LVRP) 250 ms Atrial

Ventricular Pacing Chamber BiV Right Ventricular

2868 Software Version: 4.07

P162 Firmware Version: B_v1.02.00(4.01)

© 2016 **Boston Scientific Corporation** or its affiliates. All rights reserved. Page 1 of 2

2.5 V @ 0.4 ms

3.0 V @ 0.4 ms

AGC 0.25 mV

AGC 0.6 mV

Clinician Signature:

Settings (Continued)

Brady/CRT Settings

LV Offset 0 ms Sensitivity

Left Ventricular AGC 1.0 mV

Leads Configuration (Pace/Sense)

Atrial Bipolar/Off
Right Ventricular Bipolar
Left Ventricular LVring>>RV / LVtip>>LVring

All Events Since Last Reset (04 Jun 2018)

26 May 2020 10:22	NonSustV at 163 min ⁻¹ , Nonsustained
29 Apr 2020 05:28	NonSustV at 155 min ⁻¹ , Nonsustained
31 Aug 2019 06:49	NonSustV at 166 min ⁻¹ , Nonsustained
27 Jul 2019 01:11	NonSustV at 165 min ⁻¹ , Nonsustained
07 Mar 2019 21:06	NonSustV at 159 min ⁻¹ , Nonsustained
30 Nov 2018 10:37	NonSustV at 136 min ⁻¹ , Nonsustained
05 Nov 2018 13:35	NonSustV at 143 min ⁻¹ , Nonsustained
25 Oct 2018 00:58	NonSustV at 128 min ⁻¹ , Nonsustained
02 Sep 2018 05:41	NonSustV at 163 min ⁻¹ , Nonsustained
03 Aug 2018 22:41	NonSustV at 145 min ⁻¹ , Nonsustained
_	

2868 Software Version: 4.07

P162 Firmware Version: B_v1.02.00(4.01)

© 2016

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 2 of 2

Clinician Signature: