

ZOOM ® View™ Report Created 22 Jul 2015

QUICK NOTES ® Report

Date of Birth N/R N/R N/R

Device AUTOGEN ICD D174/191431

Tachy Mode Monitor + Therapy

Last Office Interrogation

N/R

Implant Date N/R

My Alerts

There are no alerts to display.

Events Since Last Reset (22 Jul 2015)

There are no events to display.

Battery OK

Approximate time to explant: > 8 years
Charge Time N/R s

Last Capacitor Re-form N/R

One Year Remaining

Previous Session Most Recent

526 Ω

Ventricular

Leads Data

Intrinsic Amplitude N/R mV N/R mV 15.2 mV @ 71 min⁻¹

Pace Impedance N/R Ω N/R Ω

Implant

N/R N/R N/R

Pace Threshold N/R V @ N/R ms N/R Auto 0.4 V @ 0.4 ms

Shock Vector

Shock Impedance N/R Ω N/R Ω 74 Ω

Brady Counters Since Last Reset (22 Jul 2015)

Ventricular 0% Paced

Settings

Ventricular Tachy Settings

VF 230 min⁻¹ ATP 41J, 41Jx6 VT 160 min⁻¹ Burst Ramp 41J, 41Jx4

VT-1 140 min⁻¹ Monitor Only

Brady Settings

Mode VVI Pacing Output

Lower Rate Limit 40 min⁻¹ Ventricular 3.5 V @ 0.4 ms

V-Refractory (VRP) 250 ms Sensitivity

Ventricular AGC 0.6 mV

Leads Configuration (Pace/Sense)

Ventricular Bipolar

2868 Software Version: 3.05 D174 Firmware Version: E_v1.02.00(1.01) © 2014

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 1 of 1

Clinician Signature: