Scientific Scientific

System Fault Warning Date of Birth N/R N/R N/R

ZOOM ® ViewTM

Tachy Mode Device

INCEPTA ICD F160/101210 Implant Date Last Office Interrogation 07 Jun 2017

Report Created 24 Apr 2018

Warning Details

Voltage is too low for projected remaining capacity.

Contact Technical Services with code 1003

1-800-CARDIAC (North America) or contact your local Boston Scientific representative.

F160 Firmware 2868 Software Version: 4.04

Version: B_v1.02.00(4.01)

or its affiliates. All rights reserved. **Boston Scientific Corporation** Page 1 of 1 © 2016

Clinician Signature: