

ZOOM ® View™	Report Created 18 Nov 2020

QUICK NOTES ® Report

Date of Birth N/R N/R N/R

Device INCEPTA CRT-D P162/111609

Tachy Mode Off

Last Office Interrogation

25 May 2020 Implant Date

mpiani ⊅a **N/R**

My Alerts

♦ 18 Nov 2020 10:14 Ventricular Tachy mode set to value other than Monitor+Therapy

18 Nov 2020 10:14 Check LV Lead

Battery

◆ Battery capacity depleted on O2 Jun 2020
 Charge Time 16.1 s One Year Remaining Last Capacitor Re-form 02 Aug 2020 16:36



Settings

Ventricular Tachy Settings

Ventricular Tachy Therapy is disabled

Brady/CRT Settings

Mode	VVI	Pacing Output	
Lower Rate Limit	50 min ^{−1}	Right Ventricular	2.2 V @ 0.4 ms
RV-Refractory (RVRP)	250 ms	Left Ventricular	3.0 V @ 0.4 ms
LV-Refractory (LVRP)	250 ms	Sensitivity	
Ventricular Pacing Chamber	BiV	Atrial	AGC 0.25 mV
LV Offset	0 ms	Right Ventricular	AGC 0.6 mV
		Left Ventricular	AGC 1.0 mV

Leads Configuration (Pace/Sense)

Atrial Bipolar
Right Ventricular Bipolar
Left Ventricular LVtip>>LVring

2868 Software Version: 4.08

P162 Firmware Version: B_v1.02.00(4.01)

© 2016

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 1 of 1

Clinician Signature: