

ZOOM ® View™	Report Created 11 Jan 2016
--------------	----------------------------

QUICK NOTES ® Report

Date of Birth N/R N/R N/R

Device VITALIO MRI J275/101893

Last Office Interrogation **26 Jan 2015**

Implant Date

My Alerts

There are no alerts to display.

Events Since Last Reset (02 Jun 2014)

11 Jan 2016 10:57 Tachy at 175 min⁻¹
11 Jan 2016 10:56 Tachy at 166 min⁻¹
See last page for full list of Events Since Last Reset.

Battery OK

Approximate time to explant: 9.5 years
Magnet Rate 100 min⁻¹

One Year Remaining Explant

Leads Data Implant Previous Session Most Recent N/R N/R N/R >25.0 mV @ 158 min⁻¹ Intrinsic Amplitude N/R mV 22.9 mV Pace Impedance $N/R \Omega$ 552 Ω 588 Ω 1.1 V @ 0.4 ms Pace Threshold N/R V @ N/R ms Test Failed

Brady Counters Since Last Reset (02 Jun 2014)

Counters

% Paced 51

Settings

Tachy Settings

Tachy EGM Storage On

Detection Rate 160 min⁻¹

Brady Settings

Mode VVIR Pacing Output

Lower Rate Limit 55 min^{-1} 2.6 V @ 0.4 ms

Maximum Sensor Rate 115 min⁻¹ Sensitivity

Refractory 250 - 250 ms Fixed 2.5 mV

Leads Configuration (Pace/Sense)

Unipolar/Bipolar

All Events Since Last Reset (02 Jun 2014)

11 Jan 2016 11:03	NonSust at 164 min ⁻¹
11 Jan 2016 11:02	NonSust at 160 min ⁻¹
11 Jan 2016 11:01	NonSust at 173 min ⁻¹
11 Jan 2016 11:00	NonSust at 141 min ⁻¹
11 Jan 2016 10:59	NonSust at 165 min⁻¹
11 Jan 2016 10:59	NonSust at 178 min⁻¹
11 Jan 2016 10:59	NonSust at 140 min⁻¹
11 Jan 2016 10:58	NonSust at 142 min⁻¹
11 Jan 2016 10:57	Tachy at 175 min ⁻¹
11 Jan 2016 10:57	NonSust at 161 min ⁻¹
11 Jan 2016 10:56	Tachy at 166 min ⁻¹
11 Jan 2016 10:54	NonSust at 176 min ⁻¹
11 Jan 2016 10:53	NonSust at 159 min ⁻¹
11 Jan 2016 10:53	NonSust at 164 min ⁻¹
11 Jan 2016 10:52	NonSust at 164 min⁻¹
10 Jan 2016 20:46	Tachy at 131 min ⁻¹

2869 Software Version: 2.02

J275 Firmware Version: D_v1.02.00(1.01)

© 2014

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 1 of 2

Clinician Signature:

All Events	Since Last Reset ((Continued)	(02 Jun 2014)

ı	Events	Since Last	Reset	(Continue	a) (U2 Jun 1
	10 Jan	2016 20:46		Tachy a	t 153 min ⁻¹
	10 Jan	2016 20:38		Tachy a	t 190 min ⁻¹
	10 Jan	2016 20:37		Tachy a	t 170 min ⁻¹
	10 Jan	2016 20:35		-	t 162 min ⁻¹
		2016 20:34		-	t 175 min ⁻¹
		2016 20:33		-	t 163 min ⁻¹
		2016 20:31		-	t 168 min ⁻¹
		2016 20:31		-	t 147 min ⁻¹
		2016 20:28		-	t 178 min ⁻¹
		2016 20:27		-	t 185 min ⁻¹
		2016 20:27		-	
				-	t 166 min ⁻¹
		2016 20:23		-	t 163 min ⁻¹
		2016 20:20		-	t 166 min ⁻¹
		2016 20:19		-	t 152 min ⁻¹
		2016 17:07		-	t 169 min ⁻¹
		2016 17:04		-	t 189 min ⁻¹
		2016 10:37		-	t 168 min ⁻¹
		2016 09:23		•	t 183 min ⁻¹
		2016 09:22		•	t 184 min ⁻¹
		2016 09:19		-	t 168 min ⁻¹
		2016 09:18		Tachy a	t 169 min ⁻¹
		2016 09:13		Tachy a	t 174 min ⁻¹
	09 Jan	2016 09:12		Tachy a	t 175 min ⁻¹
	09 Jan	2016 08:50		Tachy a	t 136 min ⁻¹
	09 Jan	2016 08:47		Tachy a	t 175 min ⁻¹
	09 Jan	2016 08:45		Tachy a	t 173 min ⁻¹
		2016 03:43		-	t 174 min ⁻¹
		2015 17:53		-	t 155 min ⁻¹
	27 Dec	2015 11:27		-	t 186 min ⁻¹
		2015 11:25		-	t 172 min ⁻¹
		2015 11:23		-	t 162 min ⁻¹
		2015 11:22		-	t 186 min ⁻¹
		2015 11:18		•	t 175 min ⁻¹
		2015 11:14		•	t 151 min ⁻¹
		2015 11:14			t 183 min ⁻¹
		2015 15:46 2015 15:46		•	t 174 min ⁻¹
		2015 13:40 2015 12:19			t 183 min ⁻¹
		: 2015 12:19 : 2015 12:09			
					t 171 min ⁻¹
		2015 12:03			t 171 min ⁻¹
		2015 12:02		•	t 169 min ⁻¹
		2015 11:59		•	t 189 min ⁻¹
		2015 11:56		•	t 178 min ⁻¹
		2015 11:55		•	t 175 min ⁻¹
		2015 11:52			t 186 min ⁻¹
		2015 11:52			t 146 min ⁻¹
		2015 11:48			t 168 min ⁻¹
		2015 11:43			t 186 min ⁻¹
	26 Jan	2015 13:34		RV Auto)

2869 Software Version: 2.02

J275 Firmware Version: D_v1.02.00(1.01)

© 2014

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 2 of 2

Clinician Signature: