

ZOOM ® View™	Report Created 02 Oct 2014
--------------	----------------------------

Combined Follow-up Report

Date of Birth N/R N/R N/R

Device AUTOGEN ICD D174/101582

Tachy Mode Monitor + Therapy Last Office Interrogation

N/R

Implant Date N/R

My Alerts

There are no alerts to display.

Events Since Last Reset (02 Oct 2014)

There are no events to display.

Battery OK

> Approximate time to explant: > 8 years Charge Time N/R s

> Last Capacitor Re-form N/R

One Year Remaining

Explant

Leads Data Implant Previous Session Most Recent N/R N/R N/R Ventricular Intrinsic Amplitude N/R mV N/R mV >25.0 mV @ 59 min⁻¹ Pace Impedance $N/R \Omega$ $N/R \Omega$ 502 Ω Pace Threshold N/R V @ N/R ms N/R Auto 0.5 V @ 0.4 ms **Shock Vector** Shock Impedance $N/R \Omega$ $N/R \Omega$ Ω 08

Settings

Ventricular Tachy Settings

VF 220 min⁻¹ ATP 41J, 41J, 41Jx6 160 min⁻¹ Burst VT 31J, 41J, 41Jx4 Ramp

Brady Settings

Mode VVI Pacing Output 40 min⁻¹ Ventricular Lower Rate Limit

V-Refractory (VRP) 250 ms Sensitivity

Ventricular AGC 0.6 mV

3.5 V @ 0.4 ms

Leads Configuration (Pace/Sense)

Ventricular **Bipolar**

Rate Adaptive Pacing

Minute Ventilation **Passive** Accelerometer **Passive**

2868 Software Version: 3.04 D174 Firmware Version: E_v1.02.00

© 2010 Boston Scientific Corporation or its affiliates. All rights reserved. Page 1 of 4

Clinician Signature:

Rhythm ID Update					
Last Successful Con	npletion	02 Oct 2014 12:35			
Trends					
Events		Jul 14	Aug 14	Sep 14	
	v				
	Other				
Activity Level		Jul 14	Aug 14	Sep 14	
•					
	%				
Heart Rate		Jul 14	Aug 14	Sep 14	
Max		jui 14	Aug 17	3cp 14	
Mean	min ⁻¹				
Min					
Respiratory Rate	1	Jul 14	Aug 14	Sep 14	
Max					
Median Min	rpm				
IVIIII					
AP Scan		Jul 14	Aug 14	Sep 14	
Ai Ocali					
	events/h				
	,				
R-Wave (V)	j	Jul 14	Aug 14	Sep 14	
Amplitude					
	mV				
V Pace Impedance		Jul 14	Aug 14	Sep 14	
•					
	Ω				
V Dage Threehold		Jul 14	Aug 14	Sep 14	
V Pace Threshold		jui 14	Aug 17	3cp 17	
	v				
	Ť				
Shock Impedance	I	Jul 14	Aug 14	Sep 14	
	Ω				

2868 Software Version: 3.04 D174 Firmware Version: E_v1.02.00 © 2010

Boston Scientific Corporation
or its affiliates. All rights reserved.


Page 2 of 4

Clinician Signature:	


Ventricular Tachy Counters	Since Last Reset 02 Oct 2014	Device Totals	
Ventricular Episode Counters			
Total Episodes	0	0	
Treated			
VF Therapy	0	0	
VT Therapy	0	0	
VT-1 Therapy	0	0	
Commanded Therapy	0	0	
Non-Treated			
No Therapy Programmed	0	0	
Nonsustained Episodes	0	0	
Other Untreated Episodes	0	0	
Ventricular Therapy Counters			
ATP Delivered	0	0	
ATP % Successful	0	0	
Shocks Delivered	0	0	
First Shock % Successful	0	0	
Shocks Diverted	0	0	
Brady Counters	Reset Before Last	Since Last Reset	
	N/R	02 Oct 2014	
Counters			
% V Paced	0	0	
Intrinsic Promotion			
Rate Hysteresis			
% Successful	0	0	

Clinician Signature:

Histograms Reset Before Last (N/R)



Histograms Since Last Reset (02 Oct 2014)



Clinician Signature: