

ZOOM ® View™	Report Created 05 May 2016	
Combined Follow-up Report		

KRÍZ, Karel

Date of Birth 30 Aug 1954

Device AUTOĞEN X4 CRT-D G179/136339 Tachy Mode Monitor + Therapy

Last Office Interrogation

23 Mar 2016 Implant Date 12 Oct 2015

My Alerts

a 05 May 2016 19:59 Check LV Lead

Events Since Last Reset (12 Nov 2015)

25 Apr 2016 13:30 ATR at 127 min⁻¹, Avg V Rate in ATR: 124 min⁻¹ ATR at 73 min⁻¹, Avg V Rate in ATR: 79 min⁻¹ 08 Apr 2016 08:34

See last page for full list of Events Since Last Reset.

Battery	OK

Approximate time to explant: 7 years Charge Time 9.5 s Last Capacitor Re-form 20 Jan 2016 10:08

One Year Remaining

		Explant $lacksquare$	
Leads Data	Implant 12 Oct 2015	Previous Session	Most Recent
Atrial			
Intrinsic Amplitude	N/R mV	7.6 mV	4.6 mV
Pace Impedance	N/R Ω	829 Ω	766 Ω
Pace Threshold	N/R V @ N/R ms	1.0 V @ 0.4 ms	No data collected
Right Ventricular			
Intrinsic Amplitude	N/R mV	13.9 mV	8.7 mV @ 101 min ⁻¹
Pace Impedance	N/R Ω	391 Ω	352 Ω
Pace Threshold	N/R V @ N/R ms	0.8 V @ 0.4 ms	No data collected
Left Ventricular			
Intrinsic Amplitude	N/R mV	4.4 mV	2.8 mV
Pace Impedance	N/R Ω	731 Ω	558 Ω
Pace Threshold	N/R V @ N/R ms	1.1 V @ 0.4 ms	No data collected
Shock Vector			
Shock Impedance	N/R Ω	55 Ω	46 Ω

Sett	ings

Ventricular Tachy Settings				Atrial Tachy Settings	
VF	230 min ⁻¹ ATP		36J, 41J, 41Jx6	ATR Mode Switch 170 min	1 DDI
VT	185 min ^{−1} Burst	Ramp	31J, 36J, 41Jx4		

Brady/CRT Settings			
Mode	DDD	Pacing Output	
Lower Rate Limit	65 min ⁻¹	Atrial	3.0 V @ 0.4 ms
Maximum Tracking Rate	130 min ⁻¹	Right Ventricular	3.0 V @ 0.4 ms
Paced AV Delay	220 - 250 ms	Left Ventricular	4.0 V @ 0.4 ms
Sensed AV Delay	165 - 190 ms	Sensitivity	
A-Refractory (PVARP)	240 - 280 ms	Atrial	AGC 0.25 mV
RV-Refractory (RVRP)	230 - 250 ms	Right Ventricular	AGC 0.6 mV
LV-Refractory (LVRP)	250 ms	Left Ventricular	AGC 1.0 mV
Ventricular Pacing Chamber	BiV	Leads Configuration (Pace/Sense)	
LV Offset	-60 ms	Atrial	Bipolar
		Right Ventricular	Bipolar
		LV (Pace)	LVRing3>>Can
		LV (Sense)	LVTip1>>LVRing2

Rate Adaptive Pacing Minute Ventilation

Passive

2868 Software Version: 3.07 G179 Firmware Version: E_v1.02.00(2.01)

© 2014 Boston Scientific Corporation or its affiliates. All rights reserved. Page 1 of 9

Settings (Continued) Brady/CRT Settings


Rate Adaptive Pacing Accelerometer


Passive

2868 Software Version: 3.07 G179 Firmware Version: E_v1.02.00(2.01) © 2014

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 2 of 9






2868 Software Version: 3.07 G179 Firmware Version: E_v1.02.00(2.01) © 2014


Boston Scientific Corporation
or its affiliates. All rights reserved.


Page 4 of 9




Ventricular Tachy Counters	Since Last Reset 12 Nov 2015	Device Totals	
Ventricular Episode Counters			
Total Episodes	1	3	
Treated			
VF Therapy	0	0	
VT Therapy	0	0	
VT-1 Therapy	0	0	
Commanded Therapy	0	0	
Non-Treated			
No Therapy Programmed	0	0	
Nonsustained Episodes	1	3	
Other Untreated Episodes	0	0	
Ventricular Therapy Counters			
ATP Delivered	0	0	
ATP % Successful	0	0	
Shocks Delivered	0	0	
First Shock % Successful	0	0	
Shocks Diverted	0	0	
Brady/CRT Counters	Reset Before Last	Since Last Reset	
	12 Oct 2015	12 Nov 2015	
Counters			
% A Paced	16	40	
% RV Paced	98	95	
% LV Paced	99	98	
Intrinsic Promotion			
Rate Hysteresis			
% Successful	0	0	
Atrial Burden			
Atrial Burden %	<1	1	
Episodes by Duration			
< 1 minute	1	6	
1 min - < 1 hr	2	5	
1 hr - < 24 hr	1	7	
24 hr - < 48 hr	0	0	
> 48 hr	0	0	
Total PACs	26.9K	265.6K	
Ventricular Counters			
Total PVCs	1.8K	28.1K	
Three or More PVCs	10	0	
Clinical Counters	Since Last Reset 12 Nov 2015	Device Totals	
MRI Counters	0	0	


Histograms Reset Before Last (12 Oct 2015)





Histograms Since Last Reset (12 Nov 2015)





2868 Software Version: 3.07 G179 Firmware Version: E_v1.02.00(2.01) © 2014

Boston Scientific Corporation
or its affiliates. All rights reserved.

Page 7 of 9

Clinician Signature:		


Heart Rate Variability

Combined Follow-up Report

ZOOM ® View™


Last Measure for 24-hour period ending 07 Apr 2016 13:06

% of Time Used DDD 73 Mode 29 % Sensed AV Delay Footprint 165 - 190 ms **SDANN** 113 ms Ventricular Pacing Chamber BiV LV Offset -60 ms



Reference-measured for 24-hour period ending 13 Oct 2015 14:05

DDD % of Time Used 91 Footprint 35 % Sensed AV Delay 160 - 180 ms **SDANN** Ventricular Pacing Chamber 118 ms BiV LV Offset 0 ms



2868 Software Version: 3.07

G179 Firmware Version: E_v1.02.00(2.01)

© 2014 Boston Scientific Corporation or its affiliates. All rights reserved. Page 8 of 9

All Events Since Last Reset (12 Nov 2015)

05 May 2016 16:24	PMT at 130 min ⁻¹
05 May 2016 16:17	PMT at 130 min ⁻¹
05 May 2016 16:16	PMT at 130 min ⁻¹
05 May 2016 09:44	PMT at 130 min ⁻¹
05 May 2016 09:27	PMT at 130 min ⁻¹
25 Apr 2016 19:40	NonSustV at 186 min ⁻¹ , Nonsustained
25 Apr 2016 13:30	ATR at 127 min ⁻¹ , Avg V Rate in ATR: 124 min ⁻¹
08 Apr 2016 08:34	ATR at 73 min ⁻¹ , Avg V Rate in ATR: 79 min ⁻¹
31 Mar 2016 06:12	ATR at 67 min ⁻¹ , Avg V Rate in ATR: 71 min ⁻¹
09 Mar 2016 08:45	ATR at 188 min ⁻¹ , Avg V Rate in ATR: 88 min ⁻¹
19 Jan 2016 10:50	ATR at 225 min ⁻¹ , Avg V Rate in ATR: 80 min ⁻¹
19 Jan 2016 10:40	ATR at 224 min ⁻¹ , Avg V Rate in ATR: 107 min ⁻¹
19 Jan 2016 10:18	ATR at 224 min ⁻¹ , Avg V Rate in ATR: 88 min ⁻¹
19 Jan 2016 09:56	ATR at 228 min ⁻¹ , Avg V Rate in ATR: 93 min ⁻¹
19 Jan 2016 06:33	ATR at 216 min ⁻¹ , Avg V Rate in ATR: 89 min ⁻¹
18 Jan 2016 22:05	ATR at 221 min ⁻¹ , Avg V Rate in ATR: 71 min ⁻¹

2868 Software Version: 3.07 G179 Firmware Version: E_v1.02.00(2.01) © 2014
Boston Scientific Corporation
or its affiliates. All rights reserved.
Page 9 of 9