Callahan Auto & Diesel
255 West Main Street
Mesa, AZ 85201
(480) 969-3332
info@callahanautoaz.com
https://callahanautoaz.com

Estimate for RO #13304

Service Advisor: Mitch Callahan
Date Created: 02/02/26 at 04:22 PM MST
Client: EA- Restoration
Vehicle: 2022 GMC Sierra 3500 HD Denali

EA- Restoration Phone: (480) 787-1401 Email: billing@EA-restoration.com	**2022 GMC Sierra 3500 HD Denali 6.6L 8Cyl DIESEL L5P Turbocharged** VIN: 1GT49WEY9NF171892 License: V2A 0TH Color: White Odometer In: 80735 / Out: 80735	**RO # 13304** PO # - Key Tag: P3 Time-In: 02/02/26 at 04:22 PM MST Save Parts: No

Client concerns:

- Filled up on the way to work, truck died in the lot, water in fuel light came on and truck would no re-start
- Preston scanned codes, so far its matching contaminated fuel issue but unit is stuck in neutral and has parking brake on. Ensure the unit does not roll into the wall but batteries need charged and possible shift cable hooked back up. DO NOT TRY TO START, WE NEED TO GET FUEL SAMPLE ON CLEAR WATER BOTTLE THATS CLEAN AND DRY AND ALSO USE SCAN TOOL TO TEST FUEL PRESSURE

1 - Inspection

Tech: L Cervantes

Note: Vehicle arrived with a stall/no-start condition following refueling. Initial visual inspection and safety check performed. Vehicle was found secured with parking brake applied and transmission in a neutral state. Batteries were found to require charging to allow accurate testing. Vehicle was stabilized to prevent unintended movement. No attempt was made to start the engine due to suspected fuel contamination. Vehicle prepared for diagnostic testing and fuel system evaluation.

Labor:	information gathering	1.00 hrs	$0.00
✓ **Approved on 02/02/26 at 04:22 PM MST**		*0*	**0**

2 - Diagnostic testing and post repair verification and relearn

Tech: L Cervantes

Note: Vehicle was brought in with a stall/no-start concern shortly after refueling. A full diagnostic scan was performed and revealed multiple fuel system fault codes related to fuel pressure performance and fuel pump control operation. Due to the nature of the failure and fault pattern, system safeguarding procedures were performed, including battery disconnect and fuel system depressurization, to prevent internal engine or fuel system damage. Fuel system testing and inspection were required to verify low-pressure fuel delivery, evaluate pump control operation, and confirm fuel quality before any further engine operation. Diagnostic findings indicated fuel contamination, and further operation was halted to prevent additional damage.

Associated DTCs:

P1089-00 – Fuel Rail Pressure Performance During Deceleration Fuel Cut-Off

P129B-00 – Fuel Pump Driver Control Module System Voltage Low

P129F-00 – Fuel Pump Driver Control Module Fuel Pump Speed Signal Incorrect

Labor:	Diagnostic Confirmation & System Safeguarding	3.00 hrs	$585.00
☐ **APPROVE** or ☐ **DECLINE**			**$585.00**

3 - Fuel System Decontamination: Engine-Side Components
Tech: E Glosch

Note: Fuel system inspection and fuel sampling confirmed diesel exhaust fluid (DEF) contamination within the fuel system. DEF contamination causes internal corrosion and crystallization and cannot be safely corrected by flushing or partial repair. Per GM service information and industry standards, affected fuel system components must be replaced without reuse or internal inspection due to the risk of delayed or repeat failure. This operation includes removal and replacement of engine-side high-pressure and low-pressure fuel system components, including the high-pressure fuel pump, fuel injectors, fuel rails, high-pressure fuel lines, fuel cooler, engine-side return lines, and all required seals, gaskets, and one-time-use fittings. Fuel system priming is performed following component replacement. Fuel tank replacement is addressed separately per GM contamination guidelines.

Due to the extent of DEF contamination, GM service information requires replacement of affected fuel system components without internal inspection or reuse, as damage may not be visible until failure occurs. Photographic documentation and retained fuel sample are available upon request for insurance review.

	Remove and replace engine-side high-pressure and low-pressure fuel system components due to DEF contamination- Includes:		
	Remove and replace high-pressure fuel pump		
	Remove and replace all fuel injectors		
Labor:	Remove and replace fuel rails and high-pressure fuel lines	25.00 hrs	$4,875.00
	Remove and replace fuel cooler		
	Remove and replace engine-side fuel return lines		
	Replace required seals, gaskets, and one-time-use fittings		
	Fuel system priming following component replacement		
	Fuel Disposal & Hazardous Material Handling-		
	Contaminated diesel fuel was drained from the fuel tank and fuel system and handled in accordance with hazardous material handling procedures. Fuel was captured, labeled, stored, and prepared for proper disposal through an approved waste handling service. Disposal costs are based on the estimated volume of contaminated fuel removed.	1.00 hrs	$195.00
	Post-repair verification & road test and Aftertreatment system verification and readiness check		
	Following completion of fuel system repairs, the fuel system was primed and verified for proper operation. Engine was started and allowed to reach operating temperature, and idle stability was confirmed. Scan tool verification was performed to confirm no active or pending diagnostic trouble codes. A road test was completed to verify drivability. Aftertreatment system readiness was monitored per GM guidelines, including exhaust temperature monitoring and confirmation of proper SCR, NOx, and regeneration system operation. No abnormal conditions were noted at the time of verification.	1.50 hrs	$292.50
Parts:	new fuel	10	$47.50
	FILTER,FUEL	1	$147.36
	MODULE KIT,FUEL TANK FUEL PUMP	1	$252.02
	SEAL,FUEL SENDER(O RING)	1	$31.09
	COOLER,FUEL	1	$130.10
	PIPE,FUEL HIGH PRESSURE	4	$284.48
	PIPE,FUEL HIGH PRESSURE	4	$277.76
	INJECTOR,HIGH PRESSURE DIESEL FUEL	8	$3,113.76
	VALVE,FUEL PRESSURE RELIEF - LH	1	$252.32
	RAIL,FUEL INJECTION FUEL - LH	1	$409.05
	HOSE,FUEL INJECTION FUEL RETURN	1	$48.68
	PIPE,FUEL INJECTION FUEL RETURN - RH	1	$167.06
	HOSE,FUEL INJECTION FUEL RETURN	1	$35.61
	RAIL,FUEL INJECTION FUEL - RH	1	$387.17
	SENSOR,FUEL PRESSURE	1	$265.91
	GASKET,EXHAUST GAS RECIRCULATION COOLER PIPE	1	$17.44
	GASKET,EXHAUST GAS RECIRCULATION PIPE	3	$54.72
	GASKET,EXHAUST GAS RECIRCULATION VALVE COOLER BYPASS VALVE	1	$19.14
	GASKET,EXHAUST GAS RECIRCULATION PIPE	1	$55.81
	GASKET,EXHAUST GAS RECIRCULATION VALVE	1	$53.89
	SEAL,UPPER INTAKE MANIFOLD	1	$25.34
	WASHER,TURBOCHARGER OIL FEED PIPE	2	$36.30
	PIPE,FUEL INJECTION FUEL RETURN - LH	1	$177.64
	PUMP,HIGH PRESSURE DIESEL FUEL	1	$826.14

☐ **APPROVE** or ☐ **DECLINE** *Subtotal $12,478.79 + est. Tax $590.65* **$13,069.44**

4 - Fuel tank and chassis fuel system replacement (per GM contamination guidelines)
Tech: E Glosch

Note: Due to confirmed DEF contamination, GM service information requires replacement of the fuel tank and all chassis-mounted fuel system components exposed to contaminated fuel. This operation includes removal and replacement of the fuel tank, fuel tank sending unit, in-tank fuel pump module, fuel filler and vent hoses, EVAP-related hoses, and all chassis fuel supply and return lines from the tank to the engine. Components are replaced to eliminate the risk of residual contamination, as DEF crystallization may not be visible internally and can cause future system failure if reused.

	Fuel Tank & Chassis Fuel System Replacement- Includes:		
	Remove and replace fuel tank		
Labor:	Remove and replace fuel tank sending unit and in-tank fuel pump module	4.50 hrs	$877.50
	Remove and replace fuel filler and vent hoses		
	Remove and replace chassis fuel feed and return lines (tank to engine)		
	Reinstall system with new seals and fittings		
Parts:	HOSE,FUEL TANK FILLER	1	$156.46
	HOSE,FUEL TANK FILLER VENT	1	$108.22
	PIPE,FUEL RETURN	1	$126.20
	PIPE,FUEL FEED	1	$162.80
	SENSOR KIT,FUEL LEVEL	1	$103.22
	SEAL,FUEL SENDER(O RING)	1	$31.09
	TANK,FUEL	1	$1,152.66
	HOSE,EVAPORATIVE EMISSION	1	$133.64
	PIPE,FUEL FEED	1	$181.93

☐ APPROVE or ☐ DECLINE *Subtotal $3,033.72 + est. Tax $178.97* **$3,212.69**

RO Fees

Fees:	Shop supplies		$40.00
	Hazmat		$25.00
	Contaminated fuel disposal for 25 gallons $10/gallon		$250.00
		Subtotal	**$315.00**

I hereby authorize the above repair work to be done along with parts, materials and HazMat. I hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. An "Express Mechanic's lien" is hereby acknowledged on above vehicle to secure the amount of repairs thereto. I understand that by signing this, or a verbal over the phone, I approve for repairs to be performed and agree to the price estimate and that you are allowing Callahan Automotive to continue on repairs. I also agree to waive my warranty and not hold Callahan Auto & Diesel liable on any and all work that failed due to supplying my own parts and/or not following recommendations from Callahan Auto & Diesel. No refunds for services rendered.
TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within 5 days from the date I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise prior to repairs beginning. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Total Repair Order & Signature:

Total Labor:	$6,825.00
Total Parts:	$9,272.51
Total Fees:	$315.00
Subtotal:	**$16,412.51**
Taxes:	$772.94
Grand Total:	**$17,185.45**
BALANCE DUE:	**$17,185.45**

X