

NATIONAL RAILWAY AUTHORITY

AI TRACK INSPECTION REPORT

Report ID: INSP-SAMPLE-101
Date: 2026-07-23 16:41:11
Status: DEFECTIVE

Overall Status	**DEFECTIVE**	**Max Severity**	**Critical**
Avg Confidence	98.2%	**Inference Time**	18.5 ms

Visual Inspection & Defect Localization

Original Rail Track Image	YOLOv8 Bounding Box Detection
	

Detected Defects & Maintenance Recommendations

Defect Type	Confidence	Severity	Bounding Box (x1,y1,x2,y2)	Maintenance Recommendation
Rail Crack	98.2%	**Critical**	[120, 85, 340, 290]	Immediate inspection and rail replacement required.
Missing Fastener	94.5%	**High**	[400, 150, 480, 220]	Install missing fasteners immediately to maintain gauge stability.

This automated report was generated by the AI-Powered Smart Railway Inspection Platform using YOLOv8 Computer Vision. Verified by Authorized Railway Engineer. Confidential Document.