THERMAL REPORT

INSPECTION REPORT

Property: Residential Building

Location: Kolkata

Living Room:

- Visible cracks on wall
- Paint peeling observed

Bedroom:

- Water leakage on ceiling
- Mold growth detected