





```
DOSBox 0.74-3, Cpu speed: 3000 cycles, Frameskip 0, Program: CURSOR - December 2 Severe Errors

C:\MASM>edit cursor.asm
```

C:\MASM>masm cursor;; Microsoft (R) Macro Assembler Version 5.00 Copyright (C) Microsoft Corp 1981-1985, 1987. All rights reserved.

0 Warning Errors 0 Severe Errors

Microsoft (R) Overlay Linker Version 3.60

51658 + 464886 Bytes symbol space free

Copyright (C) Microsoft Corp 1983-1987. All rights reserved.

LINK : warning L4021: no stack segment C:\MASM>cursor

enter x-co-ordinate: 10 enter y-co-ordinate: 5

C:\MASM>link cursor::

