Information regarding Camera Views

Kindly note,

The camera views available here are just for reference w.r.t to their position along the Hackathon loop. Their view angle might not comply exactly with the view of the videos provided for them.

This could be due to various reasons, most likely of which is that the cameras have been shifted since their initial installation. Due to this reason, we suggest participants validate the view of the cameras via other methods as well, such as Street View in Google Maps.

A few of the camera views where we have found this inconsistency: (NORTH- 952) 18TH CROSS BUS STOP SAMPIGE ROAD MALLESHWRAM.pdf (NORTH- 954) 18TH CROSS BUS STOP MARGOSA ROAD MALLESHWRAM.pdf (NORTH - 1126) STAY WLL LODGE NEW BEL KGE LAYOUT, SANJAYNAGAR.pdf (NORTH - 1132) DEVASANDRA SIGNAL TEJA BAR NEW BEL ROAD, SANJAYNAGAR (PSSANJAYNAGAR).pdf (NORTH- 1210) MATTIKERE JUNCTON (PS YESHWANTHPURA).pdf (NORTH - 1354) KUVEMPU CIRCLE (PS-JALAHALLI).pdf

Please write to us at Hackathon.cdpg@fsid-iisc.in if you find any further issues.

All the best!