



Fatigue-Resistant Weld Design

**POOR FATIGUE
RESISTANCE**



Sharp toe angle
High reinforcement

**GOOD FATIGUE
RESISTANCE**



Smooth toe blend
Low reinforcement