


# Powder Metallurgy Process Flow


## 1. POWDER PRODUCTION



*Atomization,  
reduction, or  
electrolysis*




## 2. BLENDING



*Mix with lubricants  
and additives*




## 3. COMPACTION



*Press at  
400–700 MPa*



## 4. SINTERING



*Heat to 70–90%  
of melting point*