


Meshing Gears: Driver and Driven



KEY PRINCIPLE:

Small gear drives large gear → Speed DOWN, Torque UP