


PV Limit Curves for Common Bushing Materials

Operating point must fall BELOW the curve for the selected material



Material — Bronze (PV=50,000) — Nylon (PV=5,000) — PTFE-Lined (PV=15,000) — Sintered Bronze (PV=35,000)