

# Progressive Die Stamping – Multiple Stations

Station 1  
Pilot Holes



Station 2  
Piercing



Station 3  
Forming



Station 4  
Coining



Station 5  
Cutoff

