

The P-F Curve

Different sensor types detect failure at different positions on the

