
Straightness Control Example
Feature must remain within 0.3 mm total straightness
Deviation (mm)
20
15
10
5
0
0.0
2.5
5.0
7.5
10.0
Distance (mm)
type
Perfect (0.0 mm)
With 0.3 mm Tolerance