Common Gear Failure Modes

Bending Fatigue



Crack at root fillet
from cyclic loading

Surface Pitting



Surface fatigue
from contact stress

Adhesive Wear



Material loss from
insufficient lubrication