Meshing Gears: Driver and Driven



KEY PRINCIPLE:

ear drives large gear −> Speed DOWN, Torque UP