
PV Limit Curves for Common Bushing Materials
Operating point must fall BELOW the curve for the selected material
Sliding Velocity V (ft/min)
500
400
300
200
100
0
0
1000
2000
3000
4000
5000
Bearing Pressure P (psi)
Exceeds Nylon
PV limit!
Safe
operating point
Safe for all
Material
Bronze (PV=50,000)
Nylon (PV=5,000)
PTFE−Lined (PV=15,000)
Sintered Bronze (PV=35,000