
T–s Diagram: Ideal Rankine Cycle
Temperature, T (°C)
400
200
0
0.0
2.5
5.0
7.5
Specific Entropy, s (kJ/kg·K)
3
Turbine in
Critical
Point
Boiler (2–>3)
Turbine
(3–>4)
Pump
(1–>2)
2
1
4
mp out
ser out
Condenser (4–>1)
Turbine out