
Manufacturing Process Selection Guide
Geometric Complexity Capability (Low to High)
High
Medium
Low
3D Printing
Investment Casting
Machining
Sand Casting
Die Casting
Stamping
Welding
Low
Medium
High
Typical Production Volume (Low to High)
Process Family
Additive
Casting
Forming
Joining
Subtractive