How Shrinkage Cavities Form



Blue arrows show solidification direction (outside−in)